

FORM 54
[Sec Rule 150(a) and (2)]
Accident Information Report

1. Name of the Police Station: Kalimpong PS (Reang P.P.)
2. CR. No. /Traffic Accident Report: Kalimpong PS Case No.295/22 Dtd. U/S- 279/337/338 IPC.
3. Date, Time and Place of the accident: On 21.11.2022 at about 08.00 hrs at 27TH Mile ,NH-10 under PS/Dist. Kalimpong.
4. Name and full address of the Injured / deceased: **Details of Injured persons:** Jitendra Behera (44) s/o Lt.Gopal Behera of G-4,Sai Enclave,Jyoti Nagar,Sevoke Road,Siliguri. (Office Address-Deputy Manager (Elect) ,Lanco Teesta Hydro Power Ltd.Teesta -VI H.E. Project, Singtam, Balutar,East Sikkim.)
5. Name of the hospital to which he/she was removed: Rambh Rural Hospital and Neotia Hospital Siliguri,
6. Registration Number of vehicle and the type of the vehicle: Unknown Vehicle
7. Driving License particulars: Driving License No. -Nil-
8. Name and address of the owner of the vehicle. -Nil-
9. Name and address of the Insurance Company with whom the vehicle was insured and the particulars of the Divisional Officer of the said Insurance company: -Nil-
10. Insurance Policy / Insurance Certificate and the date of validity of the Insurance Policy/ Insurance Certificate: -Nil-
11. Registration particulars of the vehicle (Class of vehicles): -Nil-
12. Route Permit Particulars: Permit No. Nil
13. Action taken if any, and the result thereof: Registered : Kalimpong PS Case No.295/22 Dtd. U/S- 279/337/338 IPC.

(Under Section 154 Cr. P.C.)

Dist. Kalimpang P.S. Kalimpang Year 2022 FIR No. 295/22 Date 21-11-22
 i) Act. Sections ii) Act. IPC Sections 279/337/338
 (iii) Act. Sections (iv) Others Acts & Sections.

(a) Occurrence of Offence : Day Date From 21-11-22 Date To

Time Period Time From 08:00 Am Time To

(b) Information received at P.S. Date 21-11-22 Time 21:45 hrs.

(c) General Diary Reference : Entry No(s) 978 Time 21:45 hrs.

Type of Information :

Written / Oral

Place of Occurrence : (a) Direction and Distance from P.S. 25 km / Saeella Beat No. 5400-75

(d) Address 2E Nile Fatak, Kalimpang.

(e) In case outside limit of this Police Station, then the

Name of the P.S. District

Complainant / Informant :

(a) Name Ruben Subba

(b) Father's / Husband's Name Sp. Jibon Subba

(c) Date / Year of Birth : (d) Nationality

(e) Passport No. Date of Issue : Place of Issue

(f) Occupation

(g) Address Teesta Vally, Upper Gomaj- B! Rangli Rangliot, dist. Jangalm

Details of known / suspected / unknown accused with full particulars unknown Tata Sumo

(Attach separate sheet, if necessary) : Vehicle (Passenger Carrier)

Reasons for delay in reporting by the Complainant / Information

Particulars of properties stolen / involved (Attach separate sheet, if necessary) :

Total value of properties stolen / involved

Inquest Report / U.D. Case No., if any

FIR Contents (Attach separate sheets, if required) : The Original Written Complaint is treated as FIR is enclosed herewith & signature over leaf.

Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took up the

investigation / directed ASI - Ram Krishna Das of Rangli P. to take up

investigation / refused investigation / transferred to P.S. on point of

jurisdiction. FIR read over to the Complaint/ Informant, admitted to be correctly recorded and a copy given to the Complainant /

Informant free of cost.

14. Signature / Thumb impression of the Complainant / Informant

Signature of the Officer-in-Charge

Name : SARAN SARKI

Rank : STATION POLICE, KPA P.S.

15. Date & Time of despatch to the court :

सेवा में,
थाना प्रभारी
रिमाडू, पी.पी.
कालिम्पोङ्ग

ता:- 21/11/2022

विषय :- F.I.R.

महाशय, म रुबेन सुब्बा पिता जीवन सुब्बा निवासी टिस्टा भैल्ली अप्पा
कम्पैट थाना रंगली - रंगलीयट जिला दाजीलिंग, म 27# माईल फाटक
को नजदीकमा सुन्ताला बिक्री गर्नु अनि म तपाईलाई यो लिखित
जानकारी दिरहेहु कि आज 21/11/2022 को दिन बिहान अनुमानिक
8:00 बजोति सञ्च बाईक जसको नम्बर MNDSB8580 टिस्टा
तर्फ गरिरहेको बेला अनि उल्टा दिसाबाट सिलिगुडी तर्फ गरिरहेको
सञ्च सेतो रंगको अज्ञात नम्बर Passenger बाँक्ने टाटा सुमोले
Overtake गरिरहेको बेला उक्त मोटर-साईकललाई धक्का
दिएर बाटोमा लडायो र टाटा सुमो गाडी चैं सिलिगुडी
तर्फ तीव्रगति मा भागियो, यस घटनामा मोटर-साईकलको
चालाकलाई धेरै चोट लागेको हुनाले रम्बी अस्पतालमा
लागियो, बादमा मैले चाल पाएकी मोटर-साईकलको चालाक
गम्भीर अवस्थामा भएकोले गर्दा रम्बी Hospital देखि
सिलिगुडी रेफर गरियो।

यस उक्त घटना हुनको कारण चैं अज्ञात नम्बर
भएको सेतो रंगको टाटा सुमो ड्राइवरको तीव्रगति र
लापारवाही गाडी चलाई गर्दा भएको हो।

यसर्थ तपाईलाई यो निवेदन गर्दहु कि यस
बिषयलाई मध्य नजर राखीकन कानुनी-कारवाही गरि
दिनु हवस मनी नम्र निवेदन गर्दहु।

Ruben Subba

9064048470

Received on 21.11.2022 at 20.35h

Vide Reang P.P. G.P.B. no. 495 dt. 21.11.2022

and forwarded a copy to I/C, Kalimpong

P.S. to start a special case under

proper section of law.

Received on 21/11/22 at 21.45h

Vide Reang P.P. G.P.B. no. 495 dt. 21.11.22

and started Kalimpong P.S. case

no - 295/22 dt. 21/11/22 U/S-279/331

338 IPC.

21/11/2022

Officer-in-charge
Reang Police Post
Dist- Kalimpong

Inspector-in-Charge (S. Sonki)
Kalimpong Police Station
Dist. Kalimpong

लेखक :- Manoj Kumar Gupta
9002147886



UNITED INDIA INSURANCE COMPANY LIMITED

NH 31A, DEORALI BAZAR, DEORALI, GANGTOK EAST SIKKIM
EAST SIKKIM - 737102 SIKKIM

PH: (3592) 281765 FAX: EMAIL:

PCV 4 WHEELER EXCEEDING 6 OR 3 WHEELER EXCEEDING 17
LIABILITY ONLY POLICY
POLICY NO.: 0319053122P108585888
VEHICLE NO.: SK - 01 - J - 2762

PERIOD OF INSURANCE
From 17:00 Hrs of 28/11/2022
To Midnight of 27/11/2023

Insured

MR PASSANG TSHERING KAGATEY

RONGEY, EAST SIKKIM

737101

EAST SIKKIM

SIKKIM

IMPORTANT NOTICE: KINDLY UPDATE YOUR AADHAAR NO. AND PAN/FORM 60. PLEASE IGNORE IF ALREADY UPDATED.

Agent Name	: SARAN KUMAR PRADHAN
Agent Code	: AGN1002143
Mobile/Landline Number/Email	: <u>9609064157</u> <u>sarankrpradhan@yahoo.com</u>

The genuineness of the policy can be verified through "Verify Your Policy" link at www.uiic.co.in.

For any Information, Service Requests, Claim intimation and Grievances please write to 031905@uiic.co.in

Download Customer App (www.uiic.co.in), REGD. & HEAD OFFICE, 24, WHITES ROAD, CHENNAI - 600014.

Website: <http://www.uiic.co.in>

Printed By : NIR28662 @ 28/11/2022 2:42:45 PM

Date 06-12-2022

MECHANICAL EXAMINATION REPORT

Ref.: REANG, P.P.D/R, No, 982 /2022. Dt. 04-12-2022. PS: Kalimpong.

Case No. / M.A Case No.: 295 /2022. Dated. 21-11-2022. U/S, 279 /337 /338. IPC.

Name and designation of the Motor Vehicle Inspector/Expert: Bholanath Baruri / Automobile Engineer / Mechanical Expert.

Venue and Date of Examination: Reang Police Post compound on 06-12-2022.

1. Details of the Vehicle. (Attach close view and long view photo)

- a. Make TATA MOTORS LTD.
- b. Type SUMO GOLD.
- c. Model 2014.
- d. Registration Number SK 01 J 2762.
- e. Chassis Number MAT 446 502 EEA 00516.
- f. Engine Number 497 SPTC 43 PWY 661 495.
- g. Colour WHITE.

- h. Distinguishing Features (Basically please write if the vehicle can be identified without the registration number like some specific Name / Painting on the Body / Windscreen etc)
Nil.

- 1. General Description from outside - Eye View -
 - a. Point of contact between the vehicles and signs of exchange of paint -
Nil.

- b. Description of damage caused (specify)-
There is no any damage found at the time of examination.

- c. Any other point of interest-

Front right side wheel cover is not found at the time of examination.

Condition of Brakes (Please attach Photographs) -
Are the brakes OK?

Yes ☒ No ☐

Yes ☐ No ☒

b. Are they worn out?

c. Whether the brakes show wear and tear due to sudden application of the brakes at the time of accident?

Yes ☐ No ☒

d. Are there signs of brake failure which could have lead to the accident?

Yes ☐ No ☒

3. Condition of Tyres (Please attach Photographs) -

a. Do the tyres conform to the standards stipulated in MV act 1988?

Yes ☒ No ☐

b. Are the tyres worn out or resoled?

Yes ☐ No ☒

c. Do the tyres reveal any mark of skidding due to sudden deceleration by observing the wear and tear and the groove pattern?

Yes ☐ No ☒

d. Can the condition of the tyres be held responsible for the extra distance covered even after braking?

Yes ☐ No ☒

e. Were the tyres found punctured? If yes specify whether before or after the accident collision.

Yes ☐ No ☒

There is no any puncture found at the time of examination.

4. Condition of Gears -

a. Whether the gear lever, gear pinion, gear handle and clutch were in flexible state at the time of accident?

Yes ☒ No ☐

b. Whether these parts are in sufficiently lubricated condition?

Yes ☒ No ☐

5. Condition of Steering -

a. Whether steering is adequately mobile?

Yes ☒ No ☐

b. Whether the tie rod is in perfect working condition

Yes ☒ No ☐

6. Condition of Light's-

a. Whether the Head Light / Fog Light / Indicator of the vehicle are in working condition?

Yes ☒ No ☐

b. If not, is the same due to accident or were faulty even before the accident?

Light's are working properly .

7. Condition of battery :-

What is the Condition of battery?

Battery is working properly .

SEIZURE LIST

(P. NO - 409/22)

Kalimpong P.S. 295/22. dt 21.11.2022. U/S-279/337/338 IPC

1. DATE & TIME OF SEIZURE

on 2.12.2022. at 10:10h

2. PLACE OF SEIZURE

Beang P.P

3. FROM WHOM SEIZED

Being produce by Phurba Sherpa (SS)
sloawa Sherpa of Garathang J.N.
road, Gangtok East Sikkim

4. NAME OF WITNESS

(I) Tenzing Namdul Bhutia
slo it Pintcho Bhutia
off 2nd mile. upper Chandmani
Gangtok East Sikkim

(II) Passang Tempa Bhutia
slo it Pintcho Bhutia
of - Do -

5. DESCRIPTION OF SEIZED ARTICLES : (i) one white & yellow colour sumo Gold vehicle Bearing no-SK 01J/2762 without wheel cover in front right side of the vehicle (ii) one driving licence of the driver namely phurba sherpa. validity 23.09.2031. (iii) one Authorisation letter. issued from Passang Tsh. Kagatung owner of vehicle. to driver phurba sherpa (iv) one certificate of Registration. bearing bearing no-SK 01J/2762. in the name Passang Tsh. Kagatung. (v) one certificate of Fitness of vehicle. Bearing no. SK 01J/2762 (valid up to 31.8.2023) (vi) one special trade permit no. MVD/T/112. CP dt 21.11.2022 of vehicle no-SK 01J/2762 (valid from 21.11.22. to 27.11.2022) (vii) one undischarged income certificate of vehicle no-SK 01J/2762. valid 27.11.2023 (viii) one tax receipt (ix) one petrol card (x) one judicial Agreement. letter and one PUC certificate.

6. SIGNATURE OF WITNESS

(I) Tenzing Namdul Bhutia.

(II) Passang Tempa Bhutia

Seized at about of the case

ASi - Ramkrishna, Jm
Beang P.P
Dist. Kalimpong
SEIZED BY ME
21.02-12-2022

Phurba Sherpa

BHOLANATH BARURI
AUTOMOBILE ENGINEER
MECHANICAL EXPERT
VEHICLE ESTIMATOR
(PROVED) MECH REG. NO. 1120

M/S. B.N. BARURI MECHANICAL
EXPERT AND CO.
C/O. M/S. ANIL TRADING CO.
BEVOKE ROAD, BILIGURU-734 001
DARJEELING
(WEST BENGAL GOVT.) REG. NO. L-72044

Photograph of Vehicle bearing registration no
SK 01 J 2762 TATA SUMO GOLD

Date 06-12-2022.



Bholanath Baruri
Automobile Engineer Mechanical Expert

(Signature)
06.12.2022.

Bhola Nath Baruri
Automobile Engineer
Mechanical Expert