

## FORM 54

[Sec Rule 150(a) and (2)]

## Accident Information Report

1. Name of the Police Station: Kalimpong PS (Reang P.P.)
2. CR. No. /Traffic Accident Report: Kalimpong PS Case No.206/22 dtd.29.07.2022 U/S 279/338/304(A)/427 IPC.
3. Date, Time and Place of the accident: On 29.07.2022 at about 17.30 hrs at 29<sup>TH</sup> Mile, NH 10 under Reang PP Kalimpong P.S.
4. Name and full address of the injured / deceased: Injured person: Prem Pradhan (40) s/o Bal Bahadur Pradhan of Teesta Deogram PS/Dist.Kalimpong and  
Deceased person: Lakpa Sherpa (59) s/o Lt.Nima Sherpa of Teesta D.I.Fund PS/Dist.Kalimpong.
5. Name of the hospital to which he/she was removed: Kalimpong District Hospital.
6. Registration Number of vehicle and the type of the vehicle: 1) Tata tipper truck bearing no.WB-78-3784 and 2) Honda Grazia Scooty bearing no.WB-79-A-2942.
7. Driving License particulars:Driving License No.WB-22249 B 566 in the name of Ripan Mahanta s/o Jagadish Mahanta of Tripalijote,Matigara, Darjeeling.(Valid upto 15.11.2022)
8. Name and address of the owner of the vehicle-(Tata Tipper Truck)-Krishna Chhetri s/o Lt.Laxuman Chhetri of Kalijhora Parijat Nagar, Sevoke, Dist.Darjeeling.
9. Name and address of the Insurance Company with whom the vehicle was insured and the particulars of the Divisional Officer of the said insurance company: Tata AIG Insurance Coy.Ltd. Regd. Office-15<sup>th</sup> floor,Tower A, Peninsula Bussiness Park,Ganpatrao Kadam Marg,off Senapati Bapat Marg,Lower Parel,Mumbai-400013.(Tata Tipper Truck bearing No. WB-78-3784)
10. Policy / Insurance Certificate and the date of validity of the Insurance Policy/ Insurance Certificate Policy No.01602088440200 valid upto-19.11.2022)
11. Registration particulars of the vehicle (Class of vehicles): Goods Carrier (Tipper )  
(a)Registration No.WB-78-3784 (b) Engine No-91D63779665  
(c) Chassis No.MAT449053K5D07735.
12. Permit Particulars: Permit No.WB/78/GP/HGP/2019/144,Valid upto:17.10.2024( All W.B)
13. Action taken if any, and the result there of: Registered Kalimpong PS Case No.206/22 dtd.29.07.2022 U/S 279/338/304(A)/427 IPC . Seized the Tata Tipper Truck alongwith documents and also Scooty.

Surbini Hood

[Signature]

31/07/2022

Officer-in-charge  
Reang Police Post  
Dist- Kalimpong

# FIRST INFORMATION REPORT

(Under Section 154 Cr. P.C.)

4106

Dist. Kalimpang P.S. Kalimpang Year 2022 FIR No. 206/22 Date 29.7.22  
 i) Act \_\_\_\_\_ Sections \_\_\_\_\_ ii) Act IPC Sections 279/338/304(A)/427  
 (iii) Act \_\_\_\_\_ Sections \_\_\_\_\_ (iv) Others Acts & Sections \_\_\_\_\_  
 (a) Occurrence of Offence : Day Thursday Date From 28/7/22 Date To \_\_\_\_\_  
 Time Period \_\_\_\_\_ Time From 12-30 hrs. Time To \_\_\_\_\_  
 (b) Information received at P.S. Date 29.7.2022 Time 00-25 hrs.  
 (c) General Diary Reference : Entry No(s) 1419 Time 00-25 hrs.  
 Type of Information : \_\_\_\_\_ Written / Oral \_\_\_\_\_  
 Place of Occurrence : (a) Direction and Distance from P.S. 26 km / South Beat No. 1410 - 21  
 (d) Address 29th Mile, Kalimpang.

(e) In case outside limit of this Police Station, then the

Name of the P.S. \_\_\_\_\_ District \_\_\_\_\_

Complainant / Informant :

(a) Name Poorn Pradhan  
 (b) Father's / Husband's Name Shri - Bal Bahadur Pradhan  
 (c) Date / Year of Birth \_\_\_\_\_ (d) Nationality \_\_\_\_\_  
 (e) Passport No. \_\_\_\_\_ Date of Issue \_\_\_\_\_ Place of Issue \_\_\_\_\_  
 (f) Occupation \_\_\_\_\_  
 (g) Address 29th Mile, Deoghar B + D, Kalimpang.

Details of known / suspected / unknown accused with full particulars Driver of offending Vehicle  
 (Attach separate sheet, if necessary) : bearing Registration No - WB-TS/3284 (Tripper)

Reasons for delay in reporting by the Complainant / Information

Particulars of properties stolen / involved (Attach separate sheet, if necessary) :

Total value of properties stolen / involved \_\_\_\_\_

Inquest Report / U.D. Case No., if any Vid - Kalimpang B + D Case No - 80/22 dt: 28.7.2022

FIR Contents (Attach separate sheets, if required) : The Original written Complaint which is treated as FIR is enclosed here with reproduced over leaf.

Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took up the investigation / directed SI - T. T. Bhattacharya of Rearing P.P. to take up investigation / refused investigation / transferred to P.S. \_\_\_\_\_ on point of jurisdiction. FIR read over to the Complainant / Informant, admitted to be correctly \_\_\_\_\_ recorded and a copy given to the Complainant / Informant free of cost.

14. Signature / Thumb impression of the Complainant / Informant

Signature of the Officer-in-Charge Inspector-in-Charge  
Kalimpang Police Station  
Dist. Kalimpang

Name : SARAN SARKIRank : No. STOF POLICE, KALIMPANG P.S.

15. Date &amp; Time of despatch to the court :

दिनांक: 28.07.2022

सेवामा,

आफिसर-इन-चार्ज

रियाङ्ग पुलिस आउटपोस्ट

रियाङ्ग, रम्मी बजार।

जिल्ला-कालिम्पोंङ

Received on-29.7.2022 at 00-25 hrs  
vide KPA HQD EWB-1419 & 29.7.22  
and started Kalimpong Dist  
WB-206/22 & 29.7.22 (S-279)  
338/204(K)/42 EIPC.

Inspector-in-Charge  
Kalimpong Police Station  
Dist. Kalimpong

लेखक:

राजन कुमार देवी

पिता-ब्रजवीर देवी

रिस्वा पुन

DOB: 21.11.1966

Ph-7908426514

महाराज, विषय: चालकको लापरवाहीले स्कुटीलाई टक्कर हानेपछि स्कुटीको पछाडी बसेको व्यक्तिको मृत्युबारे जानकारी अनि चालकलाई उचित कार्यवाहीको माग।

महाराज,

म प्रेम प्रधान, पिता श्री बलबहादुर प्रधान, रिस्वा देवग्राम

निवासी हजुरलाई जानकारी गरउन चाहन्छु कि आज दिनांक 28.07.22,

बिहिवारको दिन म अनि मेरो साथी लाम्पा शेर्पा रम्मीबाट आफ्नो

इपुटी सकेर स्कुटीमा रिस्वा फर्किदै थियौं। लगभग साँझको 5:30 बजे

29 भाइलको पहिरो आइपुग्ग लाग्दा पछिबाट एकदमै लापरवाहीसित

आइरहेको रिप्पर नं WB78 3784 ले अचानक हामी चढेको स्कुटी-

नं WB79A 2942 लाई टक्कर हानेपछि म रुकीर अनि लाम्पा शेर्पा अर्कोतिर

लड्यौं। स्कुटी पुर्णरूपले क्षतिग्रस्त भयो। दुर्घटना हुनेसाथ मैले

देखै अनुसार श्री लाम्पा शेर्पाको टाउको गाडीको चक्कामा परेको थियो

अनि टक्करो चक्काले लाम्पा शेर्पाले लगाएको हेलमेटलाई चक्का दिदां

सङ्क्रम भएका छिलेले उसको आखां नजिक गम्भीर चोट लाग्यो।

थसपछि तुरन्तै मैले लाम्पा शेर्पालाई उठाएर सिलीगुडीबाट आइरहेको

रिस्वा हृष्णग्राभ निवासी श्री बुद्ध साकीको वेगनार कारमा हालैर कालिम्पोंङ

जिल्ला अस्पताल पन्याउँ जहाँ उनलाई मृत घोषित गरियो।

थसरी एक लापरवाह चालकको लापरवाहीले मेरो ज्यान

जोरिवममा परेको, मेरो साथी श्री लाम्पा शेर्पाले ज्यान गुमाउनु परेको

अनि स्कुटी पुर्णरूपले क्षतिग्रस्त बनाएकोमा मैले न्याय पाऊं अनि

चालकलाई उचित कार्यवाही भई गरियोस् अनि यो निवेदन मेरा

तापछि विश्वासी

Shree Pradhan

(प्रेम प्रधान)

पिता, बलबहादुर प्रधान

रिस्वा देवग्राम

Received on  
28.07.22 at 23.25 hrs  
vide Rang P.O.D.O. No.  
641 dt. 28.07.2022  
and forwarded the  
same to I/C KPA, P.S.  
to start a separate  
case under relevant  
Section of law.

दुर्घटनामा परेको स्कुटी

नं - WB 79A 2942

Signature

28/07/2022

Officer-in-charge

Rang Police Post

Dist. Kalimpong

सम्पर्क: 8637094496

**BHOLANATH BARURI**  
AUTOMOBILE ENGINEER  
MECHANICAL EXPERT  
VEHICLE ESTIMATOR  
WEST BENGAL GOVT REG. NO. 1138

Photograph of Vehicle bearing registration no  
**WB 79 A 2942 HONDA GRAZIA**

**M/S. B. N. BARURI MECHANICAL  
EXPERT AND CO.**  
C/O. M/S. ANIL TRADING CO.  
BEVKE ROAD, SAUTUR-734 001  
DARJEELING  
(WEST BENGAL GOVT) REG. NO. L-72044

Date: **04-06-2022**



**Bholanath Baruri**  
Automobile Engineer Mechanical Expert

*(Signature)*  
**Bhola Nath Baruri**  
Automobile Engineer  
Mechanical Expert

doccasol lokpo sheepa (m/s anil trading co.)

(7)

Kalinpong PS U/D Case No. 907/22 Dt 29/7/22.

# POST-MORTEM REPORT

(P.R.B. Form No. - 55 Vide Rule 284)

STATION Kalinpong  
29 day of July 2022

No. 5372

| Name, Sex, Age and Caste              | Whence brought-Village and Thana. | Name of constable by whom brought and names of relatives accompanying | Date and hour of   |          |             | Information furnished by Police | By whom identified before the Medical Officer. |
|---------------------------------------|-----------------------------------|-----------------------------------------------------------------------|--------------------|----------|-------------|---------------------------------|------------------------------------------------|
|                                       |                                   |                                                                       | Despatch           | Arrival  | Examination |                                 |                                                |
| LAKPA SHERPA<br>59 yr / Buddhist male | Tecote D. I. Kun<br>PS Kalinpong  | C/304<br>Prabhat Jang                                                 | 29/7/22<br>12 noon | 10:30 am | 10:40 am    | As per police request           | C/304<br>Prabhat Jang                          |

N.B. Observe the state of all the organs and when no disease or injury is found write "Healthy"

I-EXTERNAL APPEARANCE

| 1. Condition of subject-stout, emaciated decomposed, etc. | 2. Wounds - position, size character.                                                                                         | 3. Bruises - position, size and nature. | 4. Marks of ligature on neck, dissection etc. |
|-----------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-----------------------------------------------|
| Average build<br>Rigor mortis +                           | Large abrasion 6" x 4" in Rt forearm<br>Bruises on (R) ankle.<br>Bruises over (R) Shoulder Jt.<br>Lacerated injury on (R) Eye | Superficial                             | None                                          |

II- CRANIUM AND SPINAL CANAL

| 1. Scalp - Skull and vertebrae.                                      | 2. Membrane. | 3. Brain and spinal Cord - (The spinal canal need not be examined unless any indication of disease or injury exists.)           |
|----------------------------------------------------------------------|--------------|---------------------------------------------------------------------------------------------------------------------------------|
| Depressed # of frontal bone (R)<br>Subdural hemorrhage (2 cm x 2 cm) | Congested    | On opening the skull, subdural hemorrhage (2 cm x 2 cm) over (R) frontal bone. E. Intracerebral hemorrhage in (R) frontal lobe. |

III- THORAX

| 1. Walls, ribs and Cartilages.                         | 2. Pleura  | 3. Larynx and Trachea. | Right lung | Left lung | Pericardium | Heart                                                  | Vessel |
|--------------------------------------------------------|------------|------------------------|------------|-----------|-------------|--------------------------------------------------------|--------|
| Sclerophoses in thoracic vertebrae T2-T7 (old disease) | Congested. |                        | Congested. |           | Congested.  | All chambers of heart are filled with dark fluid blood |        |

IV- ABDOMEN

| 1. Wall of | 2. Peritoneum | 3. Mouth, Pharynx and Esophagus | 4. Stomach and its contents                    | 5. Small intestine and its contents            | 6. Large intestine and its contents |
|------------|---------------|---------------------------------|------------------------------------------------|------------------------------------------------|-------------------------------------|
|            | Congested     | Congested.                      | undigested food particles and indigestible gas |                                                | None                                |
| 7. Liver   | 8. Spleen     | 9. Kidneys                      | 10. Bladder.                                   | 11. Organs of generation external and internal |                                     |
| Congested  |               | Congested                       | 10 ml residual urine                           | None.                                          |                                     |

V- BONES AND JOINTS

| 1. Injury                        | 2. Disease or deformity | 3. Fracture        | 4. Dislocation |
|----------------------------------|-------------------------|--------------------|----------------|
| # dislocation of (L) Shoulder Jt | As mentioned above      | as mentioned above |                |

VI- DESCRIPTION OF INJURY OR DISEASE

| OPINION OF THE MEDICAL OFFICER AS TO THE CAUSE OF DEATH                                                                                                                                                                                                                 | REMARKS BY CIVIL SURGEON |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| N.B. - in the case of wounds note whether there is any indication of the wounds being homicidal suicidal or otherwise<br>In my opinion, the cause of death is due to the effect of cerebral hemorrhage caused by Rt frontal lobe hemorrhage in (R) Subdural hemorrhage. |                          |

Assistant Surgeon of

Dr. GYANIS LOPCHA  
Medical Officer

The

29th

day of

July

2022

Civil Surgeon of  
(District PH)  
Kalinpong

Date 04-08-2022.

## MECHANICAL EXAMINATION REPORT

Ref.: REANG, P.P.D/R, No. 640 /2022. Dated. 03-08-2022.

PS: Kalimpong.

Case No. / M.A Case No.: 206 /2022. Dated. 29-07-2022. U/S, 279 / 338 / 304.A. 427.IPC.

Name and designation of the Motor Vehicle

Inspector/Expert: Bholanath Baruri / Automobile Engineer / Mechanical Expert .

Venue and Date of Examination : Reang Police Post compound on 04-08-2022 .

### I. Details of the Vehicle, (Attach close view and long view photo)

- a. Make HONDA MOTORCYCLE AND SCOOTERS INDIA PVT LTD .
- b. Type GRAZIA SCOOTY .
- c. Model 2019 .
- d. Registration Number WB 79 A 2942 .
- e. Chassis Number ME 4 JF 49 HEXW 009265 .
- f. Engine Number JF 49 EW 2020125 .
- g. Colour RED .

- h. Distinguishing Features (Basically please write if the vehicle can be identified without the registration number like some specific Name / Painting on the Body / Windscreen etc)  
Nil .

### 1. General Description from outside - Eye View -

- a. Point of contact between the vehicles and signs of exchange of paint-  
Nil .

### b. Description of damage caused (specify)-

Rear portion of scooty body, guard, left side of scooty body is badly damage and rear brake and indicator light, right side of sideview mirror is broken .

- c. Any other point of interest-

Nil .

**Condition of Brakes (Please attach Photographs) -**

a. Are the brakes OK?

Yes ☒ No ☐

b. Are they worn out?

Yes ☐ No ☒

c. Whether the brakes show wear and tear due to sudden application of the brakes at the time of accident?

Yes ☐ No ☒

d. Are there signs of brake failure which could have lead to the accident?

Yes ☐ No ☒

**3. Condition of Tyres (Please attach Photographs) -**

a. Do the tyres conform to the standards stipulated in MV act 1988?

Yes ☒ No ☐

b. Are the tyres worn out or resoled?

Yes ☐ No ☒

c. Do the tyres reveal any mark of skidding due to sudden deceleration by observing the wear and tear and the groove pattern?

Yes ☐ No ☒

d. Can the condition of the tyres be held responsible for the extra distance covered even after braking?

Yes ☐ No ☒

e. Were the tyres found punctured? If yes specify whether before or after the accident collision.

Yes ☐ No ☒

There is no any puncture found at the time of examination .

**4. Condition of Gears -**

a. Whether the gear lever, gear pinion, gear handle and clutch were in flexible state at the time of accident?

Yes ☒ No ☐

b. Whether these parts are in sufficiently lubricated condition?

Yes ☒ No ☐

**5. Condition of Steering -**

a. Whether steering is adequately mobile?

Yes ☒ No ☐

b. Whether the tie rod is in perfect working condition

Yes ☒ No ☐

**6. Condition of Light's -**

a. Whether the Head Light / Fog Light / Indicator of the vehicle are in working condition?

Yes ☒ No ☐

b. If not, is the same due to accident or were faulty even before the accident?

Light's are working properly .

**7. Condition of battery :-**

What is the Condition of battery?

Battery is working properly .

### Condition of Rear View Mirrors -

- a. Are the Rear view mirrors present inside the vehicle, and both on the left and right side of the vehicle?

Yes ☒ No ☐

### Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104)

- The 3a reflector sticker is not fitted on the rear portion of scooter body .

### 10. Condition of Speed Governors:-

- a. Whether speed governor have been installed?  
b. Are they to operational condition?  
c. Have they been tampered with?

Yes ☒ No ☐

Yes ☒ No ☐

Yes ☐ No ☒

### 11. Condition of the Wipers-

- a. Were the Wiper operational prior to accident as can be ascertained from the present condition?

Yes ☒ No ☒

Yes ☐ No ☒

### 12. Whether EDR (Even Data Recorder) present or not?

13. Whether the joining points of the Axles of the vehicle with the wheels are in proper condition or not?

Yes ☒ No ☐

### 14. Overloading -

Was the vehicle overload? if yes, further remarks.


Nil .

15. Any other specific observations to highlight the condition or possible cause of the accident -

From the Technical point of view the cause of accident of the above mentioned vehicle appears to be other than mechanical failure .

Date and time of Examination of the vehicle  
On 04-08-2022 at about 4.15.P.M.

Signature of the Mechanical Expert



Bhola Nath Baruri  
Automobile Engineer  
Mechanical Expert

# SEIZURE LIST

P.R. NO. 291/22

Kolimpur P.S. case no. 206/22 dt: 29.04.2022 u/s 249/328  
104(A) / 422 IPC  
DATE & TIME OF SEIZURE

on 20-04-2022 at 10.05 AM

PLACE OF SEIZURE

At Raong P.P.

FROM WHOM SEIZED

Being produced by Registered owner  
Krishna Chatterjee & Lt. Lakshman Chatterjee  
of Savoka Bazar P.S., Kuntlaong  
Dist. Dainjeling.

NAME OF WITNESS

- (i) Birukha Bir Loma  
& B. Singh Loma  
of Savoka Bazar  
(ii) A. Kuntlaong Dist. Dainjeling  
(iii) Lt/347 Richen Bhukha  
of Raong P.P.

5. DESCRIPTION OF SEIZED ARTICLES (i) one (01) certificate of Registration

vide Registration No. WB-28-3284 (Tata Tipper) in the name  
of Krishna Chatterjee of Kolighona Panchayat Nagar Savoka (valid upto 21.11.23)

(ii) one (01) Road permit (Part A) No. WB/28/6P/440/2019/142 in respect  
of vehicle no. WB-28-3284 (valid upto 2.10-2024).

(iii) one (01) Tata A/c insurance certificate policy no. 01602088440200  
in respect of Tata Tipper bearing no. WB-28-3284 (valid upto 19.11-2022)

(iv) one (01) P.U.C. certificate SL no. WB 04100580002208 in respect of  
vehicle no. WB-28-3284

(v) one (01) Driving license no. WB-222490566 in the name of  
Dipen Mohanta & J. Mohanta of Tupaligoto, Medigona, Dainjeling  
valid upto 15-11-2022.

6. SIGNATURE OF WITNESS

(i) Birukha Bir Loma (Signature)

(iii) Lt/347 Richen Bhukha.

Seized as sample of  
the case.

P  
M  
20/04/2022  
S.T.T. Chatterjee  
SEIZED BY ME  
Raong P.P.  
P.S. Kolimpur.

# SEIZURE LIST

P.R. NO. 298/22

Kolimping P.S. case no. 206/22 dt: 29.04.2022 12/8 299/208

DATE & TIME OF SEIZURE

on 03.08.2022 at 12.55 hr

PLACE OF SEIZURE

At Leong P.P.

FROM WHOM SEIZED

Being presented by registered owner  
Krishna Chhetri s/o. H. Laxman Chhetri  
of Leake Bazar P.S. Kanchan  
Dist. Dargajiling

NAME OF WITNESS

(1) C/21 Kanchan Sangma

(11) C/21 Richan Bhukha  
Both of Leong P.P.  
under P.S. Kolimping

5. DESCRIPTION OF SEIZED ARTICLES

one (01) Authorization letter in the name of  
Ripon Molanta s/o J. Molanta of Tuijalgata, Gowa  
Madhona Dargajiling, issued by registered owner  
Krishna Chhetri regarding authorization to drive  
the vehicle no. WB-48-2484

6. SIGNATURE OF WITNESS

(1) C/21 Kanchan Sangma

(11) C/21 Richan Bhukha

Seized as a part of the case

03/08/2022

S.I. T. B. Khola  
P.S. Leong P.P.

SEIZED BY ME

P.S. Kolimping.