

FORM 54 [Sec Rule 150(a) and (2)] Accident Information Report

1. Name of the Police Station:	Mongpung Abri under Reing Ps.
2. CR. No. /Traffic Accident Report:	Roung Ps com No 07/23 \$4.02/01/23
	Ole 139/338181.

- 3. Date, Time and Place of the accident: On or for rors sot between 14 45 h
- 4. Name and full address of the injured / deceased: Padeun Sahadin ain (624)

 Sho At Rendhoj Cini of Pshanga Panty

 Morgany under Reng B. bost. Kalinging
- 5. Name of the hospital to which he/she was removed: RAMA NURSHING HOME, SILIGURI
- 6. Registration Number of vehicle and the type of the vehicle: WB/73B 3334
 (BULERO MIKUP)
- 7. Driving License particulars: Diver Binoo Kanshi sto S. Cal Ranshi Chikhat Jot, Mani vam, Naxalbani, Drysells.

 Driving Cicenu no. WB/73 2011 0263833.

 Issum Authority C. 4. silism
- 8. Name and address of the owner of the vehicle: A run Choudhuri So Jugen rath choudhuri of Matelli Potes Metelli Dis Talpaigm
 - 9. Name and address of the Insurance Company with whom the vehicle was insured and the particulars of the Divisional Officer of the said insurance company:

10.Policy / Insurance Certificate and the date of validity of the Insurance Policy/Insurance Certificate Policy No.

11. Registration particulars of the vehicle (Class of vehicles): Registration no way

33 B 3334. Chaesin no MAIZN2GG

ASIB15878 Engin No GG91

B 42374.

12. Permit Particulars:

NIL

13. Action taken if any, and the result there of: Stanta Reing & une No.

Submitted

ASI Kuma Mah Magnag Asre Aft 05/02/22.

UITI NO. 2/ FIRST INFORMATION REPORT (Under Section 154 Cr. P.C.) PS Reans Year 2023 FIR No. 07/23 Date 02/02/23 IPC Sections 2791338 Sections......(iv) Others Acts & Sections..... rence of Offence: Day Thursday Date From 0 2 02 23 Date To Time Period At a round 13-40 hr Time From Time To (b) Information received at P.S. Date 02/02/23 Time 15.05 hrs (c) General Diary Reference : Entry No(s) S1 Time 15-05 hrs Type of Information :....... 5. Place of Occurrence: (a) Direction and Distance from P.S. South East- 45 hr Beat No. 31-67 (b) Address At front of the house of kamal kuman Farrang at Thoma Busty, Mongrong (c) In case outside limit of this Police Station, then the Name of the P.S... Complainant / Informant : (a) Name Anghite Ciri (b) Father's / Husband's Name woo Mohan Bantawa Date of Issue : Place of Issue (e) Passport No..... (f) Occupation..... (9) Address Than a Busty, Mangpany, Potrington GP, 85 Reary 7. Details of known / suspected / unknown accused with full particulars (Attach separate sheet, if necessary): Driver of the Pickup Van bearing no WB 73B3734 8. Reasons for delay in reporting by the Complainant / Information 9. Particulars of properties stolen / involved (Attach separate sheet, if necessary) : Pickup Van bearing no WB 73B3734 10. Total value of properties stolen / involved 11. Inquest Report / U.D. Case No., if any 12. FIR Contents (Attach separate sheets, if required): The eniginal written complaint 13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took ASI Kuman Taman of Mangery Applotake up investigation / refused investigation / transferred to P.S. jurisdiction. FIR read over to the Complaint/ Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost. Is on the complete

14. Signature / Thumb impression

of the Complainant / Informant

DR 30-130|23

15. Bake Complex despatch to the court:

Signature of the Officer-in-Charge, Police Station Officer-in-charge

Name: Reang Police Station
Rank: No. 92

DR. NO-136/23 Ot-03/02/23

Forms 02/02/2023

माम्यारी भाना प्रभारी निकी माना :- कालेम्पोड्स थाना :- रम्बी

विषय: - उन्तरी (Complaint) जारी संक्य WB: 738 3734को पालक प्रि

अनिकार जीरी पिन और मीहन बानतवा मङ्गपड़ मोड़ा वस्ती, पाविक्वाटार सम्मा पंचायत थाना बस्वी जिल्ला कालेम्पोड़ निवासी हक्त सम्मा पर्या करते वर्ता अराउँदा हू की आज हिनाड़ १०००। १००२ का दे समा करित हिन समा करित हिन समा करित हिन समा करित है। अने स्वी रंड्नी आई संख्य अप अने से से स्वा आई संख्य अप अने से से स्वा आई संख्य अप अने से से स्वा आई से स्व करित की पता परम बार ओरि उमेर करित की वित्र मेरी पता परम बार ओरि उमेर करित की वित्र मेरी वाकालाई मेरी काकालाई हमीले आपन्सल के से साम से सामा पर पर से साम से स

मचन्यवार |

हणुरकी विश्वाधी

PHNO-6296368160

Recei of on 02.02.23 at 14.25 hrs vide mong pong ADPC

CIDE up 628 D to 2.2 23 at 15.2 23 at

Angkila Gimi

Received vide Mohan Bantawa

Penny Ps ademo 51

Dr 02/02/23 1 storted

Penny (s care no 7/23

Dr 02/02/23 015 Officer Star.

District Walimpons



MECHANICAL EXAMINATION REPORT

Date 12-02-2023.

Ref.: MDHGPONG, ADPC, D R, No, 15 2023. Dated. 10-02-2023.

PS: Reang. Kalimpong.

Case No. / M.A Case No. 07 2023. Dated. 02-02-2023. U 5, 279 338. IPC.

Name and designation of the Motor Vehicle

Inspector/Expert: Bholanath Baruri / Automobile Engineer / Mechanical Expert.

Venue and Date of Examination: Mongpong ADPC compound on 12-02-2023.

1. Details of the Vehicle, (Attach close view and long view photo)

a. Make

MAHINDRA AND MAHINDRA LTD .

b. Type

BOLERO PICKUP VAN .

c. Model

2009 .

d. Registration Number

WB 73 B 3734

e. Chassis Number

MAIZN 2 GGA 51B 1587 .

f. Engine Number

GG91 B 42374 .

g. Colour

GREEN .

h. Distinguishing Features (Basically please write if the vehicle can be identified without the registration number like some specific Name / Painting on the Body / Windscreen

The name of ", SRI GANESH " painted on the front windshield glass.

1. General Description from outside - Eye View -

a. Point of contact between the vehicles and signs of exchange of paint-

Nil .

b. Description of damage caused (specify)-

Front left side show, bumper, mudguard is badly damage and front right wine left side head and indicator light is broken .

c. Any other point of interest-

Nil .

1	Condition of Brakes (Please attach Photographs) a. Are the brakes OK?	
	b. Are they worn out?	Yes No No
		Yes No
	c. Whether the brakes show wear and tear due to sudden application of the brakes at the time of accident?	
		Yes No
	d. Are there signs of brake failure which could have lead to the accident?	
3.		Yes No
	Condition of Tyres (Please attach Photographs)	
a.	Do the tyres conform to the standards stipulated in MV act 1988?	Yes No
	b. Are the tyres worn out or resoled?	Yes No
	c. Do the tyres reveal any mark of skidding due to sudden deceleration by observing the	
	wear and tear and the groove pattern?	Yes No No
1	d. Can the condition of the tyres be held responsible for the extra distance covered even	
	after braking?	Yes No /
e	e. Were the tyres found punctured? If yes specify whether before or after the accident	
	collsion.	Yes No V
	There is no any puncture found at the time of examinati	on .
	Ondition of Gears - Whether the gear lever, gear pinion, gear handle and clutch were in flexible state at	
	the time of accident?	Yes No
ь.	Whether these parts are in sufficiently lubricated condition?	
Co	ondition of Steering -	Yes No No
а	Whether steering is adequately mobile?	
		Yes No No
D.	Whether the tie rod is in perfect working condition	
		Yes No
Con	ndition of Lights -	Yes No No
	ndition of Lights - Whether the Head Light / Fog Light / Indicator of the vehicle are in working	Yes No No
a. V		Yes No
a. V	Whether the Head Light / Fog Light / Indicator of the vehicle are in working	
a. V c b. Ifi	Whether the Head Light / Fog Light / Indicator of the vehicle are in working ondition?	Yes No No
a. V c b. Ifi	Whether the Head Light / Fog Light / Indicator of the vehicle are in working ondition? not, is the same due to accident or were faulty even before the accident?	Yes No
a. V c b. Ifi	Whether the Head Light / Fog Light / Indicator of the vehicle are in working ondition? not, is the same due to accident or were faulty even before the accident? Light's are working properly. Except front left side	Yes No No

7.

What is the Condition of battery?

Battery is working properly .

Condition of Rear View Mirrors .

a. Are the Rear view mirrors present inside the vehicle, and both on the left and right Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104) Condition of Speed Governors:-10. a. Whether speed governor have been installed? b. Are they to operational condion? c. Have they been tampered with? 11. Condition of the Wipersa. Were the Wiper operational prior to accident as can be ascertained from the present Whether EDR (Even Data Recorder) present or not? 12. Whether the joining points of the Axles of the vehicle with the wheels are in proper 13. condition or not? 14. Overloading -Was the vehicle overload? if yes, further remarks. Nil . Any other specific observations to highlight the condition or possible cause of the 15. From the Technical point of view the cause of accident of the above mentioned vehicle appears to be other than mechanical failure. Date and time of Examination of the vehicle Signature of the Mechanical Expert On 12-02-2023 at about 1.30.P.M.

12-02-2-25, Bhola Nath Baruri

Bhola Nath Barur Automobile Engineer Mechanical Expert

GOVERNMENT OF WEST BENGAL


State Transport Department KALIMPONG RTO

FORM 38

[See Rule 62(1)]

CERTIFICATE OF FITNESS

(Applicable in the case of transport vehicles only)



Registration No

: WB73B3734

Application No.

: WB22071139325939 Inspection Fee Receipt No : WB78R22070000818

Receipt Date

: 11-Jul-2022

Chassis No

: MA1ZN2GGA91B15876

Engine No

: GG91B42374

Seating Capacity Type of Body

: 3 (Including Driver) : TRUCK (FULL BODY)

Manufacturing Year Category of Vehicle

: 2009 : LGV

Inspected on

: 11-Jul-2022

Certificate will expire on

: 13-Jul-2023 : 15-May-2023

Next Inspection Due Date

Printed on

: 12-Jul-2022 16:30:26

Inspected by (DIBYENDU ADHIKARY MVI T)

Safe Drive Save Life
No Rough Drive

A BARURI

FOMOBILE ENGINEER

MECHANICAL EXPERT

VEHICLE ESTIMATOR

WED MECH. REG. NO. 1120

Photograph of Vehicle bearing registration no WB 73 B 3734 MAHINDRA BOLERO PICKUP VAN

M/S. B. N. BARURI MECHANICAL EXPERT AND CO. C/O. M/S. ANIL TRADING CO. SEVOKE BOAD, SLIGURI-734 001 DAR. SELING (WEST BENGAL GOVT) REG. NO. L-72044

Date....12-02-2023.










Bholanath Baruri Automobile Engineer Mechanical Expert

Decree Services Servi

29



NOTARY (GOVT, OF WEST BENGAL)

Baradighi Road Near Bharat Sevashram P.O. & P.S. Mal. Dist. Jalpaiguri Pin- 735221

Mobile: 97331 75328

NOTARIAL CERTIFICATE

(Pursuant to Section 8 of the Notaries Act, 1952 (53 0f 1952)

TO ALL TO WHOM THESE PRESENTS shall come, I. Sri Mohima Ranjan Paul duly authorised by the GOVERNMENT OF WEST BENGAL, to practice as a NOTARY at Sub-Division Mal, in the district of Jalpaiguri within the Union of India, do hereby verify, authenticate, certify, attest as under the execution of the instrument annexed hereto collectively marked "A" on its being executed, admitted and identified by the respective signatories as to the matters contained therein presented before me. According to that this is to certify, authenticate and attest that the annexed instrument "A" is the original.

POWER OF ATTORNEY

ARUN CHOUDHURI, S/O - Jagennath Choudhuri, of Matelli, P.O. & P.S. - Matelli, Dist - Jalpaiguri.

EXECUTANT

IN FAVOUR OF

MRINAL MITRA (AADHAAR NO. - 6511-4797-3745), S/O - Jahar Mitra, residing at Damdim More, P.O. - Damdim, P.S. - Mal, Dist -Jalpaiguri

ATTORNEY

AN ACT WHERE OF being requested of a Notary, I have granted these presents my NOTARIAL CERTIFICATE to serve and avail as needs or occasions shall or may require.

MOHIMA RANJAN PAUL
NOTARY

Advocate


(GOVT. OF WEST BENGAL) Regd. No. 79/2007

Executant(s) are/is identified by me.

Advocate, Mal,

Jalpaiguri

Subhasish Paul





3 0 JAN 2023

SEIZURE LIST

PR. NO. 15/23 deing & come no . 07/23 of. 02/22/23 0/ 279/339 181

1. DATE & TIME OF SEIZURE

: 02/02/23 insetween 14.45h.

2. PLACE OF SEIZURE

Bhough Busty new Water Took

FROM WHOM SEIZED

: Abandonid condition

4. NAME OF WITNESS

(1) Norma Jamany of sharga sungrung, Magning Anne

(11) Kamal Kumar Tamong of Branga Buty Mengong.

5. DESCRIPTION OF SEIZED ARTICLES

1) One (01) Down Blue Bolero Pickup hearing Registration NO. WE/728-3734.

suisid as s/R mojuly

6. SIGNATURE OF WITNESS

()लब्र नामांड

(11) 12 amal Kumar Tomas

Ag. Kerman The SEIZED BY ME

SEIZURE LIST

deung de come no. 07/22 \$7. 02/02/23 0/1 299/328/pt

DATE & TIME OF SEIZURE

2. PLACE OF SEIZURE

3. FROM WHOM SEIZED

4. NAME OF WITNESS

(1) Perrimo Sutter at Monymung open. (11) Clas Bishnu Roy.

: 04/02/2023 at 11.05km.

Mongring some.

As produce by Mainor Mitra 310 Jahan Mitta of Bomding nure 4.0. souline 15-201 Divid - Japain.

5. DESCRIPTION OF SEIZED ARTICLES :

1) One (01) R/c (original) henning Registration No. WB/73
B 3734. (Lyv-BOLERO PIKUP BE-18) in the rume of
frum Choubhuri s/o Jasenanth Chondown.

2) Contificate of Eitners valid upto 13 july 2023.

3) One (01) Copy of NUTARIAL CERTIFICATE, power of attorning Arun Chondhun sto Jagennath Chondhun of Metill 05- Metelli six- Jalpassin in favour of Mrinal Alitra 5/0 Tahan Mitra, Rambin ps-Mal six-Ja.

Blood Kanshi. seiged on 8/2 propuly.

6. SIGNATURE OF WITNESS

William Sulday

Bishu Ky

(II)



57. Ou 102/20

- W

回岛河域既經過

FORM 23 CERTIFICATE OF REGISTRATION CERTIFICATE NUMBER:

CRA 0407090

Registration No.

Registration Date: 24-Feb-2009

(ALT)

Previous Regn. No., if any

Owner's Name S/D/B/H Name

ARUN CHOUDHURI

LAGENNATH CHOUDHURI

Funt: Colour:

DIESEL

(a) Full Address (Permanent)

: METELI JALPAIGURI Ariffer

No Me

(b) Full Address (Temporary)

T/A- B. KUJUR-S/O. MOREN PHANSIDEWA DIST- DARJEELING -

Cubic Capacity: Polistion compliance: 2523 CC

Garage Address

Specimen Signature of Owner

Class of Vehicle : LIGHT GOODS VEHICLE

Maker's Name

: Mam -MAHINDRA & MAHINDRA LTD LGV- BOLERO PIK UP BS-R

Type of Body

: TRUCK (FULL BODY)

Year of Manufacture

: /2009

No. of Cylinder

Chassis No. MAI NZGGABIBIBBIB

pagine No.

Horse Power

Stating Capacity

3150

Wheel Base

7.00X15=2 7.00X15=2

3 (including driver)

Registered Size of Tyres-Front Axle

Rear Axle Any other Axle

1130 kgs 1690 kgs

Registered Axle Weight-Front Axle

0 kgs 0 kgs

Rear Axle Any other Axle

1890 kgs

Unladen Weight

28-Feb-2018

Registration valid up to

23-Feb-2016

Tax Paid up to H.P.A./Lease agreement with Address HYPOTHECATION WITH U B K. GRAMIN BANK, METELI BRANCH, JALPAIGURI, .

Specimen Signature of Financer:

Follows !

Bharat Cham !!

SLIGU