

ACCIDENT INFORMATION REPORT

(Rule 150(1) of Central Motor Vehicle Rule 1989)



1. Name of the Police Station :- Kalimpong PS
2. CR No./ Traffic Accident Report (FIR/Crime No) :- Kalimpong PS Case No. 171/22 Dtd. 15.06.2022
U/S 279/337/338 IPC
3. Date, Time & Place of the Accident :- On-15/06/2022 at about 10:30 hrs.
Mamkhola NH-10 ,Kalimpong
4. Name & full Address of the injured/deceased :- Details of Injury persons.
- (i) Arun @ Indra Mani Rai (56) S/o Late Chandar Mani Rai
Of Naya Bazar PS-Naya Bazar , West Sikkim
- ii) Pawan Tamang (40) S/o Chandra Bdr. Tamang
of Dara Goan Jorethang PS Jorathang , South Sikkim
- iii) kumar Pradhan (36) S/o Birkha Bdr Pradhan
of Rhenock Alitar , East Sikkim A/P- kumek Busty PS Rangpo
East Sikkim,
- iv) Chitraj Pradhan (39) (Driver) S/o Late Bhanu Pradhan
of Kumrek Busty PS- Rangpo East Sikkim
- v) Sanjay Kami (34) (Driver) S/o Late Gopi Kami
of Sisney PS Naya Bazar , West Sikkim .
5. Name of the Hospital to which he/she was Examined/Forward :- All treated at Rangpo PHC, East Sikkim
6. Registration number & type of vehicle :- (i) SK-02-P/0269 (Zon Estilo) Car and (ii) SK01-PB/4637 (Scorpio)
7. Driving Licence Particulars :- Not yet seized Not yet seized
- (a) Name & Address of the Driver :- (i) Sanjay Kami (34) (ii) Chitraj Pradhan (39)
S/o Late Gopi Kam S/O Lt.Bhanu Pradhan
Of Sisney PS- Naya Bazar of Kumrek Busty PS- Rangpo
West Sikkim East sikkim
- (b) Driving Licence number & date of expiry :-
- (c) Address of the issuing Authority :-
- (d) Regd. No. in case of Public service vehicle :-
8. Name & Address of the owner of the vehicle :-
At the time of the Accident
- 9.(I) Name & Address of the insurance company :-
With whom the vehicle was insured & the
Particulars of the Divisional Office of the said
Insurance Company
10. Name of Insurance Policy/ Insurance Certificate :-
& the Date of Validity of the Insurance Policy/
Insurance Certificate
11. Registration Particulars of the vehicle(Class of the vehicle) :- (i) SK-02-P/0269 Zon Estilo Car and (ii) SK01-PB/4637 Scopio

12. Registration No. & Class of vehicle :- (i) SK-02-P/0269 (Zon Estilo) Car (ii) SK01-PB/4637 (Scorpio)
(i) Engine No. :- K10BN 4033986 SJH4K18900
(ii) Chassis No. :- MA3EMDE1500263560CA MA1TA2SJXH2K40051
13. Route Permit his Particulars :- N/A
14. Action taken if any & the result there on:- Kalimpong PS Case No. . 171/22 Dtd. 15.06.2022
U/S 279/337/338 IPC

Submitted


REF:- Kalimpong Ps. Case No 171/22 dtd 15-06-22
(U/s-279/337/338 IPC (Gr. No. 189/22))

1. DATE & TIME OF SEIZURE on 10-07-22 in between 15:10 to 15:45hr
2. PLACE OF SEIZURE Melli op under Kalimpong Ps.
3. FROM WHOM SEIZED from being produce by Sanjay karni
S/o Gopi karni of Sisney Soreng Ps. Naya Bazar
4. NAME OF WITNESS Naya Bazar, West Sikkim

Sanjay karni

- (i) Hemant karni 33 yr.
S/o Santosh karni of Sisney Soreng
Ps. Naya Bazar West Sikkim
- (ii) - CN/905 Thomas Subba
of Melli op, under Kalimpong Ps.
Dist Kalimpong

5. DESCRIPTION OF SEIZED ARTICLES :

- (i) - one original R/C Book of vehicle NO. SK-02-P-0269.
in the name of owner Sanjay karni
- (ii) one original insurance Certificate Policy No. - 15060731
- 22676000041 valid upto - 04-04-23.
- (iii) one PUC. of vehicle NO. SK-02-P-0269. valid upto.
- 07-10-22.
- (iv) - one original DIL NO SK 04, 2012 0000187. in the
name of Driver Sri Sanjay karni S/o Gopi karni,
of Sisney Soreng Ps. Naya Bazar West Sikkim.
valid upto - 07-11-2032.

6. SIGNATURE OF WITNESS

- (i) Hemant karni
- (iii) CN/905 THOMAS Subba.

Melli op DR No-550/22

Seized by one
[Signature]
10/07/22

SEIZURE LIST

PR No 212/22

REF: Kalimpong P.S. Case No 171/22 dtd- 15-06-22
u/s. 279/337/338 IPC. (GRM 189/22)

1. DATE & TIME OF SEIZURE on. 04/07/22 in between 11:15 to 11:35 hrs.

2. PLACE OF SEIZURE melli op under Kalimpong P.S.

3. FROM WHOM SEIZED From being produce by Chitraj Pradhan s/o Late Bhanu Pradhan of Kumrek Bursky P.S. Rangpo. East Sikkim

4. NAME OF WITNESS

- (i) - Ranjit Pradhan 24 yrs.
s/o Late Narendra K. Pradhan
of Kumrek P.S. - Rangpo, East Sikkim
- (ii) - Edwin Chethi 25 yrs.
s/o Late Rooraj Chethi.
of Mayhitar P.S. - Rangpo East Sikkim

5. DESCRIPTION OF SEIZED ARTICLES :

- (i) One original R/C. in r/o vehicle No. SK. 01-PR-4637. in the name of owner Bindhya Pradhan
- (ii) - one Insurance Certificate Policy No. 150608312161600 002010. valid upto - 21-11-22.
- (iii) - one PUC. valid upto 28/02/23.
- (iv) - one D/L No. SK-0720050012883. in the name of Driver Chitraj Pradhan s/o Lt. Bhanu Pradhan of Kumrek Bursky P.S. Rangpo East Sikkim. valid upto - 19-06-30.

6. SIGNATURE OF WITNESS

(i) Ranjit Pradhan

(ii) Edwin Chethi

Lx No S39/22
date 04/07/22



Seized by me.

(45) Binish Chapp
Rangpo melli op
Kalimpong

Issuing Office Name & Address
KALIMPONG BRANCH, BAGDHARA ROAD, NEAR CROWN LODGE, 2ND FLOOR, KALIMPONG - 734301
 Tel: Fax: 03552 255561 (0)
 GSTIN No: 19AAACN9967E120



National Insurance Company Ltd.
 Registered & Head Office: 3, MIDDLETON STREET, POST BOX NO. 9229, KOLKATA - 700 071
CERTIFICATE OF INSURANCE CUM POLICY SCHEDULE
 Form 51 of the Central Motor Vehicle Rules, 1989

Policy No: 15060731228780000041 Private Car 1 Year Liability from 15:52 Hrs of 05/04/2022 to Midnight of 04/04/2023

Insured Details
 Name: **Mr SANJAY KAMI**
 Address: **SISNEY, NAYABAZAR WEST SIKKIM, SIKKIM**
 Pincode: 737121 Telephone: 8389929644 Email: nickpg@gmail.com
 PAN No.: GSTIN No: Aadhar No:
 Channel: **KISHOR PRADHAN** Mobile: 9735016309 Email: kishorepradhan777@yahoo.com
 Aadhar: Code: 150607 / 9000166488
 PAN: XXXXXX3559

Vehicle Details

| Make & Model | Private Car MARUTI SUZUKI ZEN ESTILO LXI BSIV | Reg. No. | Engine No. | Chassis No. | Type of Body | CC | Mfg. Year | Seat Cap | Reg. District |
|--------------|---|---------------------|---------------------|---------------------------|--------------|-----|-----------|----------|---------------|
| | | SK-02-P-0269 | K10BN4032888 | NAJEMDE190203983CA | HATCHBACK | 998 | 2010 | 1+4 | WEST SIKKIM |

Geographical Area: INDIA

| FastTag ID | Vehicle IDV | Non Elec Access | Elec Access | Bi-fuel kit | Trailer | Total IDV |
|------------|-------------|-----------------|-------------|-------------|---------|-----------|
| | | | | | | |

| OD Premium Breakup in Rs. | | TP Premium Breakup in Rs. | |
|---------------------------------|---|---|-----------------|
| Basic OD Premium | - | Basic TP Premium | 2,072.00 |
| (+) Electrical Access Premium | - | (+) WC for Driver | 50.00 |
| (+) Bi-fuel kit Loading | - | (+) Wider Legal Liability to employees | - |
| (+) Geographical Area Extension | - | (+) Geographical Area Extension | 295.00 |
| (-) Vol. Excess Discount | - | (+) PA to owner driver | - |
| (-) Auto. Assoc Discount | - | (+) PA to unnamed PAX | - |
| (-) Anti-theft Discount | - | (-) Discount For Limited TPPD | - |
| (-) Other Discount | - | (+) Bi-fuel kit Loading | 2,417.00 |
| (-) NCB Discount | - | TP Total (Rounded Off) | 2,417.00 |
| (+) Nil Depreciation | - | OD Total (Rounded Off) | 2,417.00 |
| (+) Nil Depreciation Plus | - | TOTAL PREMIUM | 435.00 |
| (+) NCB Protect | - | GST | 2,852.00 |
| (+) Engine Protect | - | NET PAYABLE | |
| (+) Invoice Protect | - | Collection Number: 15060781228000000061 dated 05-Apr-2022 | |
| (+) Consumables Protect | - | Subject to IMT Endorsement No. 24,25,28 | |
| (+) Lock-Key Protect | - | | |

OD Total (Rounded Off)

IMPORTANT NOTICE:
 The insured is not indemnified if the vehicle is used or driven otherwise than in accordance with this schedule. Any payment made by the company by reasons of wider terms appearing in the certificate in order to comply with the Motor Vehicles Act, 1988 is recoverable from the insured. See the clause headed "AVOIDANCE OF CERTAIN TERMS AND RIGHT OF RECOVERY". For legal interpretation, English version will hold good.

Financier: SELF OWNED
 Prev Policy: Not Available Relation: WIFE Age: 28 Years
 Nominee Name: **BABITA KAMI**

Warranted that in case of dishonour of the premium cheque, this document stands automatically cancelled AB-INITIO.
 I hereby certify that this Certificate cum Schedule of Insurance is issued in accordance with the provisions of chapter X and chapter XI of Motor Vehicles Act, 1988.



AUTHORISED AGENT
National Insurance Co. Ltd.
 A Govt. of India Undertaking
 IRDA License No. 10280149

For:
 Renewal Contact: 97350 16309
 97757 20101
 Kishor Pradhan
 Authorised Agent
 Code: 9000166488
 National Insurance Co. Ltd.
 Jorethang

NICUBPORTAL/9000166488 05/04/2022 03:52 PM

Visit us at <https://nationalinsurance.co.in> for information on Products, Services and Grievance Redressal.
 Customer Care Toll Free Number: 1800 145 0110 Email: customer.support@nic.co.in

SEIZURE LIST

PR. No 242/22

REF: Kalimpong Ps. Case No 171/22 dtd- 15-06-22
U/S- 279/337/338 IPC. (GR No 189/22)

1. DATE & TIME OF SEIZURE on. 04/07/22 in between 11:15 to 11:35 hrs.
2. PLACE OF SEIZURE Meli op under Kalimpong Ps.
3. FROM WHOM SEIZED From being produce by Chitraj Pradhan s/o Late Bhanu Pradhan of Kumrek Busty Ps. Rangpo. East Sikkim
4. NAME OF WITNESS
(i) - Ranjit Pradhan 29 yrs.
s/o Late Narendra Kumar Pradhan
of Kumrek Ps - Rangpo, East Sikkim
(ii) - Edwin Chetty - 25 yrs
s/o Late Asoraj Chetty
of Majhitar Ps - Rangpo East Sikkim

5. DESCRIPTION OF SEIZED ARTICLES :

- (i) one original R/C. in r/o vehicle No. SK-01-PB-4637. in the name of owner Bindhya Pradhan
- (ii) one Insurance Certificate Policy No. 150608312161600 002010. valid upto - 21-11-22.
- (iii) - one PUC. valid upto 28/02/23.
- (iv) - one D/L No. SK-01 2005 0012883. in the name of Driver Chitraj Pradhan s/o Lt. Bhanu Pradhan of Kumrek Busty Ps. Rangpo East Sikkim, valid upto - 19-06-30.

6. SIGNATURE OF WITNESS

(i) Ranjit Pradhan

(ii) Edwin Chetty

IL NO 539/22
date 04/07/22



Seized by me
04/07/22
(As) Anish Chetty
Comptroller Meli op
Kalimpong.

Condition of Rear View Mirrors -

a. Are the Rear view mirrors present inside the vehicle, and both on the left and right side of the vehicle?

Yes No

9. Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104)

10. **Condition of Speed Governors:-**

a. Whether speed governor have been installed?

Yes No

b. Are they to operational condition?

Yes No

c. Have they been tampered with?

Yes No

11. **Condition of the Wipers-**

a. Were the Wiper operational prior to accident as can be ascertained from the present condition?

Yes No

12. Whether EDR (Even Data Recorder) present or not?

Yes No

13. Whether the joining points of the Axles of the vehicle with the wheels are in proper condition or not?

Yes No

14. **Overloading -**

Was the vehicle overload? if yes, further remarks.

15. Any other specific observations to highlight the condition or possible cause of the accident -

Date and time of Examination of the vehicle

Signature of the Mechanical Expert

Rhola Nath Barua
Rhola Nath Barua
Automobile Engineer
Mechanical Expert

Condition of Brakes (Please attach Photographs) -

- a. Are the brakes OK? Yes No
- b. Are they worn out? Yes No
- c. Whether the brakes show wear and tear due to sudden application of the brakes at the time of accident? Yes No
- d. Are there signs of brake failure which could have lead to the accident? Yes No

3. Condition of Tyres (Please attach Photographs) -

- a. Do the tyres conform to the standards stipulated in MV act 1988? Yes No
- b. Are the tyres worn out or resoled? Yes No
- c. Do the tyres reveal any mark of skidding due to sudden deceleration by observing the wear and tear and the groove pattern? Yes No
- d. Can the condition of the tyres be held responsible for the extra distance covered even after braking? Yes No
- e. Were the tyres found punctured? If yes specify whether before or after the accident collision.
Front right side puncture after the accident .

4. Condition of Gears -

- a. Whether the gear lever, gear pinion, gear handle and clutch were in flexible state at the time of accident? Yes No
- b. Whether these parts are in sufficiently lubricated condition? Yes No

5. Condition of Steering -

- a. Whether steering is adequately mobile? Yes No
- b. Whether the tie rod is in perfect working condition? Yes No

6. Condition of Light's -

- a. Whether the Head Light / Fog Light / Indicator of the vehicle are in working condition? Yes No
- b. If not, is the same due to accident or were faulty even before the accident?
Light's are not working properly due to accident .

7. Condition of battery :-

What is the Condition of battery?
Battery is not working properly

Condition of Rear View Mirrors -

a. Are the Rear view mirrors present inside the vehicle, and both on the left and right side of the vehicle?

Yes No

9. Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104)

10. **Condition of Speed Governors:-**

a. Whether speed governor have been installed?

Yes No

b. Are they to operational condition?

Yes No

c. Have they been tampered with?

Yes No

11. **Condition of the Wipers-**

a. Were the Wiper operational prior to accident as can be ascertained from the present condition?

Yes No

12. Whether EDR (Even Data Recorder) present or not?

Yes No

13. Whether the joining points of the Axles of the vehicle with the wheels are in proper condition or not?

Yes No

14. **Overloading -**

Was the vehicle overload? if yes, further remarks.

15. Any other specific observations to highlight the condition or possible cause of the accident -

Date and time of Examination of the vehicle

Signature of the Mechanical Expert

Rhola Nath Barua
Rhola Nath Barua
Automobile Engineer
Mechanical Expert

Particulars of witnesses to be examined:

| Name S.No | Father's/ Husband Name | Date/Year of Birth | Occupation | Address | Type of evidence to be |
|-----------------------|--|-----------------------|------------|---------|---|
| 1 | 2 | 3 | 4 | 5 | 6 |
| S.I Deepak Thapa | O/C Melli OP under Kalimpong PS | | | | Complainant 9932843791 |
| Kumar Pradhan | 36 yrs S/o Birkha Bdr Pradhan of Rhenock , Aritar PS Rhenock East Sikkim . | | | | Seizure/Witness 9932671506 |
| Ranjit Pradhan | S/O Lt Narendra Pradhan of Kumrek Busty PS-Rampoo,East Sikkim. | | | | Seizure/Witness 7319120718 |
| Adwin Chettri | S/O Lt. Dewraj Chettri of Mazitaar PS-Rampoo,East Sikkim. | | | | Witness 7478917972 |
| Hament Kami | S/O Santosh Kami of Sesney,Soreng PS-Nayabazar,West Sikkim | | | | Witness 8617550896 |
| CVF/905 Thomas Subba | of Melli OP under PS & Dist-Kalimpong | | | | Seizure/Witness 9749670389 |
| Indra Mani Rai @ Arun | S/O Lt Chandra Mani Rai of Naya Bazar PS-Naya Bazar,West Sikkim | | | | Seizure/Witness 7908123958 |
| Pawan Tamang | S/O Chandra Bdr Tamang of Dara Gaon PS-Jorthang South Sikkim | | | | Seizure/Witness 7908195978 |
| Dr Sandhya Rai | M.O In-Charge Rangpoo PHC Govt of Sikkim | | | | Seizure/Witness 7797888451 |
| Sri Bholanath Baruri | Automobile Engineer/Mechanical Expert,Sevoke Road, Siliguri PS- Bhaktinagar. | | | | Mechanical Expert 9800867580,94344047580 |
| R.O Saran Sarki | of Kalimpong PS | | | | Recording Officer 7001818113 |
| I.O ASI Dinesh Thapa | of Melli OP under Kalimpong PS | | | | Investigating Officer 8436510914 |

15. If F.R is false, indicate action taken proposed to be taken u/s 182/211 IPC.....

16. Result of laboratory analysis.....

17. **Brief fact of the case:** - The brief fact case is that on 15/06/22 at 11:15Hrs S.I Deepak Thapa O/C Melli OP under Kalimpong PS received information over telephone that an accident meet with two vehicles at near Maamkhola on NH-10 on received information he diarized the fact in Melli OP GDE No-320 Dt 15.06.22 and informed the fact to I/C Kalimpong PS over telephone and as per direction of I/C Kalimpong SI Deepak Thapa,O/C Melli op along with force left OP to work out the information. On arrival he found that two vehicles Zon Estilo car bearing Regd No-SK02P/0269 and Scorpio vehicle bearing Regd No-SK01PB/4637 lying on NH-10 near Maamkhola on damaged condition. With the help of local peoples and force SI Deepak Thapa O/C Melli OP manage to shifted the both damaged vehicles in the suitable space and traffic became under control. During local enquiry it could be learnt that the accident was occurred about 10:30 hrs due to rash and negligently driven by both vehicle drivers as a result total five persons including drivers sustained grievous injury and shifted them Rampoo PHC, Govt of Sikkim for their treatment. Over the written complaint of SI Deepak Thapa,O/C Melli OP I/C Kalimpong PS recorded the above noted case and endorsed me to investigate the case.

Dispatched on

Forwarded
Sa Gh

05. 9. 22

Inspector-in-Charge
Kalimpong Police Station
Dist. Kalimpong -

Signature of the investigating Officer
Submitting the Final Report/Charge Sheet
Name.ASI Dinesh Thapa Melli OP, PS Kalimpong


Col No-17 : During investigation of the case I visited the PO, sketched the rough map of PO with index, examined all available witnesses and patients and recorded their statement U/S 161 Crpc, I seized the both accidental vehicles and its relevant documents under proper seizure list. After collecting sufficient evidences I served the notice U/S 41(A) Crpc to the both offending drivers 1.Chitraj Pradhan 39 yrs (Driver of said vehicle No SK 01 PB 4637) S/o Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim and 2. Sanjay Kami 34 yrs (Driver of said vehicle No, SK02 P 0269)S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim. According on my notice both the offending drivers had voluntarily surrendered before Ld court and released on court bail. Further investigation of the case examined the both accidental vehicle mechanically by mechanical expert Bholanath Baruri and as per order of Ld CJM,Kalimpong both the vehicles including its relevant documents to its present registered owner except Driving Licence under proper receipt. In coure of the investigation and as well as the statement of witnesses and as per documentary evidences a prima facie charge U/S 279/337/338 IPC has been well established against both vehicle drivers 1.Chitraj Pradhan 39 yrs (Driver of said vehicle No SK 01 PB 4637) S/o Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim and 2. Sanjay Kami 34 yrs (Driver of said vehicle No, SK02 P 0269)S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim involved in this case. I consulted my superior officers O/C Melli OP and I/C Kalimpong PS regarding the merits and demerits of the case. They perused the CD's minutely and advised me to submit charge sheet U/S 279/337/338 IPC against both vehicle drivers 1.Chitraj Pradhan 39 yrs (Driver of said vehicle No SK 01 PB 4637) S/o Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim and 2. Sanjay Kami 34 yrs (Driver of said vehicle No, SK02 P 0269)S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim. Accordingly obtaining permission from my superior officers I am submitting this charge sheet vide Kalimpong PS C/S No-320/22 Dt 31.08.22 against 1.Chitraj Pradhan 39 yrs (Driver of said vehicle No SK 01 PB 4637) S/o Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim and 2. Sanjay Kami 34 yrs (Driver of said vehicle No, SK02 P 0269)S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim to face trial in open court of law. Witneeses will prove the case during trial. All may kindly be summoned during trial in open court of law. The Result of the complainant being informed by issuing notice vide B.P Form No-43.

=====

Seen & filed

I/C Kalimpong P.S.
Dt. 5.9.22

Submitted


31/08/22
(Anil Kishore)

CHARGE SHEET/FINAL REPORT

(Under section 173 Cr.P.C.)

In the court of. Ld. CJM Kalimpong

1. Dist.. **Kalimpong**....P.S ...**Kalimpong**.....Year...**2022**....FIR No-**171/2022**.....Date **15.06.2022**.
 2. **Final Report/Charge sheet No 320/2022** Date **31/08/2022**.

(i) Act Section **.279/337/338 IPC**

(ii) Other Acts and Section...

5. Type of final report: Charge Sheet/ Untraced/ Un occurred/ not Charge Sheeted for want of evidence ...**Charge Sheeted**.....
 6. If F.R unoccurred: False/ Mistake of Fact/ Mistake of Law/ Non cognizable/ Civil Nature.....
 7. If Supplementary of Original **Original**.....
 8. Name, Rank and Number (if any) of the I.O.(s)--- **ASI Dinesh Thapa, Melli OP, PS Kalimpong,**
 9. (a) Name of Complainant / Informant .. **SI Deepak Thapa (O/C) Melli OP**
 (b) Father's / Husband's Name-
 10. Date on which the complainant / Informant was informed of the result **On 01.09.2022**
 11. Detail of properties/Articles/Document recovered/Seized during investigation and relied upon (separate list can be attached, if necessary):

| SL No | Property Description | Estimate Value | Property No. | From whom/where recovered & seized | Disposal |
|-------|---|----------------|--------------|---|---|
| | .i> One light maroon colour Zon Estilo Car bearing Regd No-SK-02-P-0269 front side damaged condition with key. ii>One still colour Scorpio Vehicle bearing Regd No-SK-01PB-4637 front side damaged condition with key. | | 215/22 | As shown and produced by 1.Chitraj Pradhan 39 yrs (Driver of said vehicle No SK 01 PB 4637) S/o Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim and 2. Sanjay Kami 34 yrs (Driver of said vehicle No, SK02 P 0269)S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim | Articles Sl. No. 1 & 2 Released as per order of Ld CJM vide O/S No-6 Dt 05.07.22 & O/S No-8 Dt 12.07.22 |
| | .i> One Original Certificate of Registration in R/O vehicle No-SK-02-P-0269 in the name of owner Sanjay Kami 34 yrs S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim ii> One Original Insurance Certificate in R/O vehicle No-SK-02-P-0269 iii> One Original PUC in R/O vehicle No-SK-02-P-0269 iv> One Original Driving Licence of Sanjay Kami 34 yrs S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim bearing D/L No- SK04 20120000187 valid up to 07.11.32. | | 253/22 | On being produced by Sri Sanjay Kami 34 yrs S/o Gopi Kami of Sisney Soreng PS- Naya Bazar, West Sikkim | All Released as per order of Ld CJM vide O/S No-6 Dt 05.07.22 except item No-iv D/L |
| | i> One Original Certificate of Registration in R/O vehicle No-SK-01-PB-4637 in the name of Bidhya Pradhan W/O Chitraj Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim. ii.> One Original Insurance Certificate in R/O vehicle No-SK-01-PB-4637. iii> One Original PUC in R/O vehicle No-SK-01-PB-4637. iv> One Original Driving Licence of Chitraj Pradhan S/O Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim bearing D/L No- SK01 20050012883 valid up to 19.06.30. | | 242/22 | On being produced by Sri Chitraj Pradhan S/O Late Bhanu Pradhan of Rangpo Kumrek Busty PS Rangpo , East Sikkim | All Released as per order of Ld CJM vide O/S No-8 Dt 12.07.22 except item No-iv D/L |

DR. MOHPAL'S NURSHING HOME PVT. LTD.

Meghnad Saha Sarani, Pradhan Nagar, Siliguri - 734 003
Ph. (0353) 2519081 / 2513437

INJURY REPORT

Date: 08/08/2022

Name of the Patient:

Mr. Indramani Rai

S/O -

Late. Mr. Chandra Mani Rai

Age/Sex:

54 Years / Male

Address:

Naya Bazar , S B I Mall, Bareli,

Dist - South Sikkim, Sikkim

Date of Examination in OPD:

15/06/2022

Cause of Injury:

Road Traffic Accident

Injury Sustained:


Close Distal Radius of Right Hand

Treatment Given:

Closed Reduction Under Anesthesia & Cast

Nature of Injury:

Grievous



(Signature of the Doctor)





UNION OF INDIA Driving Licence GOVERNMENT OF SIKKIM

SK04 2012 0000187

Date of Issue 08-11-2012
Validity  07-11-2032



Date of Birth 17-06-1988


Blood Group A+

Name

SANJAY KAMI

Father's Name

GOPAL KAMI





Polres P. Cen. No. 177/2022/ST/PP-PT/2022

DATE & TIME OF SEIZURE

On 24/06/22 at 13:15 hrs.

PLACE OF SEIZURE

West-Pakthong, Algeah, Kalimantan

FROM WHOM SEIZED

Mari Ka, Temang self-luarba Temang West-Pakthong, Algeah, Kalimantan

NAME OF WITNESS

- (I) Chhataman Subba
510 Samek Hany Subba
Wkt. Pakthong, Algeah
Kalimpong
- (II) Ajay Temang
510 Laha Doyis Temang
Wkt. Pakthong Subba
Algeah, Kalimantan

Mari Kurnia Temang

DESCRIPTION OF SEIZED ARTICLES :

- 1 One Meruti Eco vehicle bearing no. WB 73A 2114 sup-wor with colour in fully damaged condition.
- 2 Rik book of vehicle bearing no. WB. 73A 2114 (original copy) owner name Jiwon Temang 510 luarba Temang, Surok Kalimantan (adjinal) Algeah, Kalimantan.
- 3 D/L of Jiwon Temang 510 luarba Temang, Surok Kalimantan (adjinal)
- 4 Duplicate copy of Inwama sufficient valid up to 06/08/2022
- 5 Copy of Tan-Teken Receipt no. WB 78 D 13080000041WB 130804 99997676

(Seized as element of the case)

SIGNATURE OF WITNESS

(I) Chhataman Subba.

(II) Ajay Temang

SEIZED BY ME
A. K. K.

(Attach separate sheet, if necessary)

13. Particulars of accused persons not charge-sheeted (suspected) : NIL

- 1) Name :
- 2) Father's / Husband's Name :
- 3) Date / Year of Birth :
- 4) Sex : v) Nationality :
- 5) Whether SC/ST : vi) Religion :
- 6) Address :
- 7) Provisional Criminal No : viii) Occupation :
- 8) Suspicion Approved :
- 9) Forwarded / Bailed by Police / Under Police Custody / Bailed by Court / In Judicial Custody/ Absconding / Proclaimed Offender :
- 10) Under Acts and Sections :
- 11) Any special remarks including reasons for not charge-sheeting :

Particulars of Witnesses to be examined:

| Sl. No. | Name | Father's / Husband's Name | Date/ Year of Birth | Occupation | Address | Type of evidence to be tendered |
|---------|------|---------------------------|---------------------|------------|---------|---------------------------------|
| | Nil | Nil | Nil | Nil | Nil | Nil |

19.If R.R. is false, indicate action taken or proposed to be taken u/s 182/211

IP.C.....

20.Result of laboratory analysis :

Brief fact of the Case : The brief fact of the case is that on 24/06/2022 AT 15:00 hrs. one Mani Kumar Tamang S/O Lt. Phurba Tamang of West Pakthang Santook GP, Algarah PS+Dist. Kalimpong came at PS. And submitted a written information to the effect that on 23/06/22 at about 15:00 hrs. his brother Jiwan Tamang while coming towards Algarah driving his own vehicle WB:79A2114 met with an accident at Pipili Dara 3rd mile Lava Road and fell down hill and he sustained major injuries vehicle was fully damaged and the accident person was rushed to Dist. Hospital Kalimpong over this written complaint started Kalimpong PS. Case no. 177/22 dtd:24/06/22 U/S 279/338 IPC and endorsed me for its investigation.

During investigation of the case I visited PO as identified by the complainant prepared rough sketch map of the PO with its index in separate sheet of paper. I had examined available witnesses and recorded their statements U/S 161 Cr P.c. I seized the damaged vehicle WB:79A2114 and its document in proper seizurelist. I sent the requisition to the Mechanical Expert for mechanical examination of the the damaged vehicle bearing no. WB:79A2114. I collected mechanical examination report of the said vehicle to ascertain the actual cause of accident.

During investigation of this case it could be learnt from the complainant Mani Kumar Tamang that injured person Jiwan Tamang was referred to Siliguri N.B.M.C. on same day i.e. on 23/06/22 and he was admitted at North Bengal Neuro Centre Pvt. Ltd. Siliguri for better treatment. Unfortunately the patient was expired on 27/06/22 in ICU Bed No.03 North Bengal Neuro Centre Siliguri over this started Pradhannagar PS. U/D Case No.43/22 dtd:27/06/22 and the surathal report was prepared by ASI, Madan Rishi of Pradhannagar PS. under Siliguri Police Commissionerate. On 27/07/2022 I collected the SCD and P.M. Report of the deceased person Jiwan Tamang S/O Lt. Phurba Tamang of West Pakthang Santook GP, Algarah PS+Dist. Kalimpong from Pradhan Nagar PS. Siliguri Commissionerate. Dr. Dibyakar Chhetri Demonstrator Deptt. of F.M. & Toxicology N.B. Medical College had opined that death was due to the effect of Head Injury, antinormem in nature. On 28/07/22 I sent the prayer for adding 304(A) and the prayer was allowed for further investigation in this case.

It is to be noted that during investigation of the case I had observed all the formalities as per law and followed all the instruction given by my superior and it came to light that due to dense foggy weather, narrow roads the vehicle bearing no. WB.79A2114 fell downhill at Pipili Dara 3rd mile Lava Road and the driver of the vehicle was seriously injured and was rushed to the District Hospital Kalimpong and again he was referred to Siliguri NBMC for better treatment. Unfortunately the patient was expired on 27/06/22 in ICU Bed No.03 North Bengal Neuro Centre Siliguri. Hence after consulting with my superior I am submitting Final Report as True in this case vide Kalimpong PS, F.R.T. No. /22 dtd. /09/2022 U/S 279/338/304 A IPC, with keeping an option the case will be reopen if any clues or evidence could be collected in future.

Dispatched at a.m. / p.m.

Forwarded

SAC

27.9.22

Inspector-in-charge
Kalimpong Police Station
Dist. Kalimpong

Submitted

As I. Ravi Lepcha
24/09/2022

ASI. Ravi Lepcha
Algarah PP, Kalimpong PS,
Dist. Kalimpong

Seen & filed

M/C Kalimpong P.S.
Dt. 27.9.22

(Under Section - 173 Cr. P.C.)

IN THE COURT OF I.D. CHIEF JUDICIAL MAGISTRATE, KALIMPONG.

Dist. Kalimpong PS. Kalimpong Year 2021 FIR No. 177/22 Date 24-06-2022

1. Dist. Kalimpong PS. Kalimpong Year 2021 FIR No. 177/22 Date 24-06-2022
2. Final Report/Charge Sheet No 544/2022
3. Date 27/09/22
4. i) Act : I.P.C. Sections : 279/338/304(A)

ii) Act :
 iii) Act :
 Sections :

5. Type of Final Report: Charge Sheet/ Untraced/ Un-occurred / Not Charge-sheeted for want of evidence.
 Charge Sheet : Sections :

F.R.T.

6. If F.R. unoccurred : False / Mistake of fact / Mistake of law / Non-cognizable / Civil nature
7. If Supplementary or Original : Original
8. Name, Rank and Number (if any) of the I.O. (S) : ASI Ravi Lepcha
 a) Name of Complainant / Informant : Dr. Anup Kumar Sarkar
 b) Father's / Husband's Name :
 9. Date on which the Complainant / Informant was informed of the result :
 10. Details of Properties / Articles/ Documents recovered / Seized during investigation and relied upon separate
 11. List can be attached, if necessary :

| Sl. NO. | Property Description | Estimated value (in Rs.) | PS. Property Register no. | From Whom/Where/Recovered or Seized | Disposal |
|---------|----------------------|--------------------------|---------------------------|-------------------------------------|----------|
| | NIL | NIL | NIL | NIL | NIL |

- 11.A) Number of accused persons charge-sheeted : NIL
- B) Number of accused persons not charge-sheeted: NIL

12. Particulars of accused persons charge-sheeted.

- 1) Name :
- 2) Father's / Husband's Name :
- 3) Date / Year of Birth :
- 4) Sex : v) Nationality : v) Religion :
- 5) Whether SC/ST : viii) Occupation :
- 6) Address :
- 7) Provisional Criminal No. :
- 8) Regular Criminal No. : xiii) Date of release on bail :
- 9) Date of Arrest :
- 10) Date on which forwarded on Court :
 11) Under Acts and Sections :
 12) Name (s) and Address(es) of sureties :
 13) Previous Convictions with case references :
 14) Forwarded / Bailed by Police / Under Police Custody / Bailed by Court / In Judicial Custody / Absconding / Proclaimed Offender :

6. Are the Rear view mirrors present inside the vehicle, and both on the left and right side of the vehicle?

Yes No

Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104)

711.

10. Condition of Speed Governor:-

a. Whether speed governor have been installed?

Yes No

b. Are they to operational condition?

Yes No

c. Have they been tampered with?

Yes No

11. Condition of the Wipers-

a. Were the Wiper operational prior to accident as can be ascertained from the present condition?

Yes No

12. Whether EDR (Even Data Recorder) present or not?

Yes No

13. Whether the joining points of the Axles of the vehicle with the wheels are in proper condition or not?

Yes No

14. Overloading -

Was the vehicle overloaded? if yes, further remarks.

711.

15. Any other specific observations to highlight the condition or possible cause of the accident -

From the Technical point of view the cause of accident of the above mentioned vehicle appears to be other than mechanical failure.

Date and time of Examination of the vehicle

On 29-06-2022 at about 2.30 P.M.

Signature of the Mechanical Expert

Bhola Nath Barui
Automobile Engineer
Mechanical Expert

Date: 30-06-2022.

MECHANICAL EXAMINATION REPORT

PS: Kallimpong.

Ref: 131/ASA, P.P, D/A, No, 175/6922, Dated, 28-06-2022.

Case No./M.A Case No.: 177/6922, Dated, 24-06-2022, V/6, P/9/B/50, I.P.G.

Name and designation of the Motor Vehicle
Inspector/Expert: Bhalanath Barui / Automobile Engineer / Mechanical Expert.

Venue and Date of Examination: At accident spot on 15th road Bhatidara 5th mile on
No. 131/ASA, P.P, D/A, No, 175/6922.

1. Details of the Vehicle, (Attach close view and long view photo)

- a. Make HONDA
- b. Type SEDAN PASSENGER CARRIER
- c. Model 2019
- d. Registration Number WB 79 A 2114
- e. Chassis Number MA 3 50L F1500728575
- f. Engine Number G 12 NR 710236
- g. Colour WHITE

h. Distinguishing Features (Basically please write if the vehicle can be identified without the registration number like some specific Name / Painting on the Body / Windscreen etc)

Nil.

1. General Description from outside - Eye View.

a. Point of contact between the vehicles and signs of exchange of paint.

Nil.

b. Description of damage caused (specify)-

Front show, bumper, saggers, engine bonnet, SED body, front and rear both side door, front and rear both side suspension, propeller shaft, radiator, engine cover is badly damaged and front windshield glass, all door window glass, both side head and front and rear both side indicator light, rear both side brake light, both side side view mirror is broken.

c. Any other point of interest.

Nil.

| Name, sex, Age and caste | Whence brought - Village and Thana | Name of constable by whom brought - names of constables accompanying | Date and hour of | | | Information furnished by Police | By whom identified before the Medical Officer |
|--|---|--|----------------------|-----------------------|----------------------|--|---|
| | | | Police Station | Arrival at dead-house | Examination | | |
| JIWAN TAMANG Male Aged 35yrs S/O Phurba Tamang | North Bengal Neuro Centre Pvt. Ltd, Pradhannagar PS | C/880 Shyamal Dutta Pradhannagar PS | 20.50hrs 27.06.22 | 13.35hrs 28.06.22 | 14.05hrs 28.06.22 | As per the Inquest Report attached with this report. | C/880 Shyamal Dutta Pradhannagar PS |

N.B. - Observe the state of all the organs and when no disease or injury is found write "Healthy"

| 1. - Condition of Subject - stout, emaciated decomposed, etc. | 2. - Wounds - position, site, character | 3. - Bruises - position, size and nature | 4. - Marks of ligature on neck, dissection, etc. |
|---|---|--|--|
| Length 5'4" Wt. 70kg Average built, moderately nourished W/A. Grey half sleeved T-shirt, black half pant, leucoplast and bandage applied over scalp, disposal napkin around waist, multicolored string with metallic "tabiz" tied around Rt. arm. Scalp hairs cut. (Eyes closed, pupils dilated fixed and cornea hazy both eyes, mouth partially open. I/V puncture wound over clavicular region of Rt. anterior chest wall and anterior aspect of Rt. elbow. RM present all over body) | Injuries: 1) Curvilinear shaped sutured surgical wound over Lt. side of forehead and scalp, extending from 1/2" above Lt. eyebrow to Lt. Frontal, Parietal and Temporal regions of scalp, just anterior to Lt. ear, 18" in length and cranial cavity deep on removing the sutures. 2) Sutured and stapled wound over Lt. Parietal and Temporal regions of scalp, 2 1/2" above Lt. ear, 3" in length and cranial cavity deep on removing the sutures and staples. 3) Sutured wound over Lt. Frontal region of scalp, 2" above Lt. eyebrow; 1 1/2" in length and muscle deep on removing the sutures. 4) Infected sutured and stapled wound over Rt. Parietal region of scalp, 4" above Rt. ear, 2" in length and muscle deep on removing the sutures and staples. 5) Scabbed grazed abrasion over Lt. Temporal region of scalp, 1" anterior and 1/2" above Lt. ear, 1" x 1/2" area. 6) Scabbed grazed abrasion over Lt. face, 1" anterior to Lt. ear, 1/2" x 1/2" area. 7) Scabbed abrasion over Lt. face, 1/2" below Lt. eye, 1" x 1/2" area. 8) Sutured wound over Lt. face, 1/2" below Lt. eye, 1/2" in length and muscle deep on removing the sutures. 9) Sutured wound over Lt. face, 1/2" below Lt. eye, 1/2" in length and muscle deep on removing the sutures. 10) Scabbed abrasion over Lt. anterior aspect of chin, 1/2" below Lt. angle of mouth, 1/2" x 1/2" area. 11) Scabbed grazed abrasion over Lt. anterior aspect of Lt. shoulder and scapular region of Lt. posterior chest wall, 8" x 6" area. 12) Bruise over | Brain and Spinal Cord - (The spinal canal need not be examined unless any indication of disease or injury exists.) | Brain: As noted above |

| 1. - Skull and Vertebrae | 2. - Membrane | 3. - Brain and Spinal Cord |
|--|----------------|----------------------------|
| Scalp & Skull: As noted above Vertebrae: Intact | As noted above | Brain: As noted above |

| 1. - Walls, ribs and Cartilages | 2. - Pleurae | 3. - Larynx and Trachea | Right Lung | Left Lung | Pericardium | Heart | Vessels |
|---------------------------------|---------------------------|-------------------------|------------|-----------|---|--|---------|
| As noted above | Pleural adhesion Lt. side | Healthy | Edematous | Edematous | Serous fluid (approx. 15ml) in pericardial cavity | Walls healthy, chambers containing fluid blood | Healthy |

| 1. - Walls | 2. - Peritoneum | 3. - Mouth, Pharynx and Esophagus | 4. - Stomach and its contents | 5. - Small intestine and its contents | 6. - Large intestine and its contents |
|----------------|-----------------|-----------------------------------|---|---|---|
| As noted above | Edematous | Healthy | Walls healthy, cavity containing only mucus | Walls healthy, cavity containing only gas | Walls healthy, cavity containing gas and faeces |

| 7. - Liver | 8. - Spleen | 9. - Kidneys | 10. - Bladder | 11. - Organs of generation, external and internal |
|------------|-------------|------------------------|-----------------------------|---|
| Congested | Healthy | Congested both kidneys | Walls healthy, cavity empty | Healthy |

| 1. - Injury | 2. - Disease or deformity | 3. - Fracture | 4. - Dislocation |
|----------------|---------------------------|----------------|------------------|
| As noted above | Nil | As noted above | Nil |

*Lateral aspect of Lt. arm, extending from Lt. shoulder, 5" x 3" area and blackish in color. 13) Old laceration over dorsal aspect of base of Rt. thumb, 1" x 1" area and muscle deep. 14) Scabbed grazed abrasion over Lt. lateral chest and abdominal wall, 7" below Lt. axilla, 6" x 4" area. 15) Bruise over Lt. lateral abdominal wall, 8" below Lt. axilla, 2" x 2" area and bluish black in color. 16) Scabbed abrasion over Lt. lateral and posterior abdominal wall, 8" x 1 1/8" area. 17) Scabbed grazed abrasion over Lt. posterior abdominal wall, 5" lateral to midline, 6" x 5" area. 18) Scabbed abrasion over dorsal aspect of Lt. wrist, 1/2" x 1/2" area. 19) Old laceration over dorsal aspect of Lt. foot, 1/2" proximal to base of Lt. 5th Toe, 1" x 1" area and muscle deep. 20) On dissecting the scalp, scalp tissue edematous with old haematoma seen over bilateral Frontal, Parietal and Temporal regions of scalp and craniotomy over Lt. Frontal, Parietal and Temporal bones, 7" x 5" area with cranial cavity exposed with evidences of intracranial haemorrhage and surgical intervention. The injuries noted above showed evidences of antemortem vital reaction. No other antemortem injury detected even on careful examination and dissection.

OPINION OF THE MEDICAL OFFICER AS TO THE CAUSE OF DEATH

REMARKS BY CIVIL SURGEON

N.B. - At the rate of wounds note whether there is any indication of the wounds being homicidal suicidal or otherwise.
Death was due to the effects of Head Injury, antemortem in nature.

Prepared by me
Assistant Surgeon of
Pradhannagar P.S.
Dr. P. P. Chatterjee
District Surgeon
Distt. - 24 P & T, Jalpaiguri

The day of 2022
Civil Surgeon of



REG. NO. BUEN 234 801
DARJEELING
(WEST BENGAL GOVT) REG. NO. L-7004

114 MARUTI EECO

Date 30-06-2022



Bholanath Baruti
Automobile Engineer Mechanical Expert

Bholanath Baruti
30-06-2022

Bhola Nath Baruti
Automobile Engineer
Mechanical Expert