

**FORM 54**  
**[Sec Rule 150(a) and (2)]**  
**Accident Information Report**

- 1. Name of the Police Station:**Reang PS
- 2. CR. No. /Traffic Accident Report:**Reang PS Case No-55/23 Dt-16.08.23 U/S 279/337/338/427 IPC
- 3. Date, Time and Place of the accident:** On 15.08.23 at 23:30 hrs at near Teesta vallyFatak under Reang PS Dist-Kalimpong
- 4. Name and full address of the injured / deceased:**
  1. PremBahaadur Kami, Male 43yrs(Driver) s/o Late BalBdrKami of Gealing, Samsing, PSNayabazar, West Sikkim.
- 5. Name of the hospital to which he/she was moved/ removed:**Rambi Rural Hospital, NBMC, Siliguri
- 6. Registration Number of vehicle and the type of the vehicle:**White Ford carbearing Registration No-WB 74AX1407
- 7. Driving License particulars:** None
- 8. Name and address of the owner of the vehicle:-**Pintu Lal s/o Late Devendra Lal of New Palpara,ShrimaSarani, Ward No 32, RabindraSarani PS Bhaktinagar, Dist- Jalpaiguri.
- 9. Name and address of the Insurance Company with whom the vehicle was insured and the particulars of the Divisional Officer of the said insurance company:**Not known
- 10. Policy / Insurance Certificate and the date of validity of the Insurance Policy/Insurance Certificate Policy No.-**Not known
- 11.Registration particulars of the vehicle (Class of vehicles):**Not known
- 12.Permit Particulars:**None
- 13.Action taken if any, and the result there of:** Case is pending for further investigation.

## FIRST INFORMATION REPORT

(Under Section 154 Cr. P.C.)



West Bengal Form No. 27  
 Kalimping P.S. Roang Year 2023 FIR No. 55/23 Date 16.08.2023  
 Sections 219/336/331/147 Ad. Sections  
 (iv) Others Acts & Sections  
 (a) Date of Offence Day Tuesday Date From 15.08.23 Date To 15.08.23  
 Time Period Time From 20:30 hrs Time To  
 (b) Information received at P.S. Date 16.08.2023 Time 11:35 hrs  
 (c) General Diary Reference Entry No(s) 463 Time 11:35 hrs  
 4. Type of Information Written / Oral  
 5. Place of Occurrence: (a) Direction and Distance from P.S. 03 km (approx) On the N.H. J.L. No. 74  
 (b) Address Near Teesta Valley Jalsik, P.S. Roang, Kalimpong  
 (c) In case outside limit of this Police Station, then the Name of the P.S. District  
 6. Complainant / Informant:  
 (a) Name Pinito Lal  
 (b) Father's / Husband's Name late Deendara Lal  
 (c) Date / Year of Birth (d) Nationality Indian  
 (e) Passport No. Date of Issue Place of Issue  
 (f) Occupation Not known  
 (g) Address Shreema Sonari, New Palana, Rabinch Sonari P.S. Shikha, Jalpaiguri  
 7. Details of known / suspected / unknown accused with full particulars (Attach separate sheet, if necessary):  
 Driver of the vehicle from Bishnukarna  
 vehicle bearing registration No- WB94AX1407  
 8. Reasons for delay in reporting by the Complainant / Information N/A  
 9. Particulars of properties stolen / involved (Attach separate sheet, if necessary):  
 Vehicle bearing registration No- WB94AX1407 (car)  
 10. Total value of properties stolen / involved N/A  
 11. Inquest Report / U.D. Case No., if any N/A  
 12. FIR Contents (Attach separate sheets, if required): The original written complaint which is treated as FIR is attached herewith / reproduced annexed.  
 13. Action taken: Since the above report reveals commission of offence(s) as mentioned at item No. 2, registered the case up to the investigation / directed by 31 Pushpa Kumar Rai Officer-in-charge, Roang Police Station, Dist-Kalimpong  
 investigation / refused investigation / transferred to P.S. jurisdiction. FIR read over to the Complainant / Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost.  
 14. Signature / Thumb Impression of the Complainant / Informant Pinito Lal.  
 Signature of the Officer-in-charge Station Roang Police Station  
 Name: S.I. Bishu Chandra Name  
 Rank: No. Sub Inspector of Police  
 15. Date & Time of despatch to the court On 17/08/2023 at 10:00 hrs

To  
The Officer Incharge  
Reang Police Station  
Kalimpong.

(Sub: Information regarding an accident)


Dear Sir,

I would like to inform you that, I Pintu  
Lat S/O Late Derendra Lat, Shreema  
Sarani New Lalpara, Rabindra Sarani  
Siliguri, Jalpaiguri. Sir I sent my  
Car on 15th August to drop my guest  
to Gangtok. At the time of returning.

Driver Mr. Prem Biswakarma S/O  
Late Bal Bahadur Biswakarma. Getting  
West Sikkim, fell Down from the NH 10  
near 27th Mile at Night 11:30 PM. Light  
Reflected on the face of driver, due  
to narrow road he disbalance and fell  
down on valley. Now he is injured  
and Hospitalized at Siliguri Civil  
Hospital.

Due to Help of Reang Police  
Station recovered the Driver and  
Sent to Siliguri Hospital. I am really  
thankful for that and I have a  
request you to please grant a permission  
to recover my Car from the valley

Received on 16.08.2023 vide Reang  
PS Case No. 463 Dt 16.08.23  
started a specific case vide Reang  
PS Case No. 55/23 Dt 16.08.2023  
U/S 279/337/338/427 IPC.

  
16/08/2023  
Officer-in-charge  
Reang Police Station  
Dist-Kalimpong

Thanking You  
Pintu Lat  
8942997577  
Siliguri.  
16th August

REQUISITION

To  
Sri Bholanath Baruri  
Automobile Engineer/Mechanical Expert  
Sevoke Road, Siliguri, P.S, Bhaktinagar.

Date:-19-08-2023.

Ref:- Reang, P.S, Case no, 55 / 2023. Dated, 16-08-2023.  
U/S, 279/338/337/427.IPC.

Sir,


Kindly arrange to examine one vehicle bearing reg no, WB-74-AX-1407.FORD ECOSPORT, which was Seized In connection with the above noted case reference and lying at Reang Police Station compound under seizure.


Mechanical examination is required for the investigation of case.

So you are requested to examine the above noted seized vehicle mechanically and give mechanical Examination report with opinion as on early date.

Thanking You

Yours Faithfully

  
SI, Pushpa Kumar Rai  
Reang Police Station  
Dist Kalimpong.

  
18.08.2023  
**Bhola Nath Baruri**  
Automobile Engineer  
Mechanical Expert

D/R No 1945/2023.  
Dated 19/08/2023.

MECHANICAL EXAMINATION REPORT

Date..21-08-2023.....

Ref.: REANG, P.S.D/R, No, 1945/2023. Dated. 19-03-2023.

PS: Reang. Kalimpong.

Case No. / M.A Case No.: 55 / 2023. Dated. 16-08-2023.

U/S, 279 / 338 / 337 / 427 . IPC.

Name and designation of the Motor Vehicle

Inspector/Expert: Bholanath Baruri / Automobile Engineer / Mechanical Expert .

Venue and Date of Examination: Reang Police Station compound on 21-08-2023.

1. Details of the Vehicle, (Attach close view and long view photo)

- a. Make  
FORD IND PVT LTD .
- b. Type  
ECOSPORT .
- c. Model  
2019 .
- d. Registration Number  
WB 74 AX 1407 .
- e. Chassis Number  
MAJAXXMRKAKC 16721 .
- f. Engine Number  
KC 16721 .
- g. Colour  
WHITE .
- h. Distinguishing Features (Basically please write if the vehicle can be identified without the registration number like some specific Name / Painting on the Body / Windscreen etc)

Nil .

1. General Description from outside - Eye View -

- a. Point of contact between the vehicles and signs of exchange of paint-

Nil .

b. Description of damage caused (specify)-

Front show, bumper, mudguard, engine bonnet, front and rear both side door, ECOSPORT body, front both side suspension, radiator, A/C system is badly damage and front both side head and indicator light, rear both side brake and indicator light, front windshield glass, all door glass is broken. both side side view mirror is broken .

c. Any other point of interest-

Nil .

2.

### Condition of Brakes (Please attach Photographs)

a. Are the brakes OK?

Yes ☐ No ☒

b. Are they worn out?

Yes ☐ No ☒

c. Whether the brakes show wear and tear due to sudden application of the brakes at the time of accident?

Yes ☐ No ☒

d. Are there signs of brake failure which could have lead to the accident?

Yes ☐ No ☒

### 3. Condition of Tyres (Please attach Photographs)

a. Do the tyres conform to the standards stipulated in MV act 1988?

Yes ☒ No ☐

b. Are the tyres worn out or resoled?

Yes ☐ No ☒

c. Do the tyres reveal any mark of skidding due to sudden deceleration by observing the wear and tear and the groove pattern?

Yes ☐ No ☒

d. Can the condition of the tyres be held responsible for the extra distance covered even after braking?

Yes ☐ No ☒

e. Were the tyres found punctured? If yes specify whether before or after the accident collision.

Yes ☒ No ☐

Front left side tyre is puncture after the accident .

### 4. Condition of Gears -

a. Whether the gear lever, gear pinion, gear handle and clutch were in flexible state at the time of accident?

Yes ☒ No ☐

b. Whether these parts are in sufficiently lubricated condition?

Yes ☒ No ☐

### 5. Condition of Steering -

a. Whether steering is adequately mobile?

Yes ☐ No ☒

b. Whether the tie rod is in perfect working condition

Yes ☐ No ☒

### 6. Condition of Lights -

a. Whether the Head Light / Fog Light / Indicator of the vehicle are in working condition?

Yes ☐ No ☒

b. If not, is the same due to accident or were faulty even before the accident?

Light's are not working properly due to accident .

### 7. Condition of battery :-

What is the Condition of battery?

Battery is not working properly due to accident .

# Condition of Rear View Mirrors -

- a. Are the Rear view mirrors present inside the vehicle, and both on the left and right side of the vehicle?

Yes ☒ No ☒

9. Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104)

Nil .

10. Condition of Speed Governors:-

- a. Whether speed governor have been installed?

Yes ☒ No ☐

- b. Are they to operational condion?

Yes ☒ No ☐

- c. Have they been tampered with?

Yes ☐ No ☒

11. Condition of the Wipers-

- a. Were the Wiper operational prior to accident as can be ascertained from the present condition?

Yes ☒ No ☐

12. Whether EDR (Even Data Recorder) present or not?

Yes ☐ No ☒

13. Whether the joining points of the Axles of the vehicle with the wheels are in proper condition or not?

Yes ☒ No ☒

14. Overloading -

Was the vehicle overload? if yes, further remarks.

Nil .


15. Any other specific observations to highlight the condition or possible cause of the accident -

In my poinion the accident occured due to cause other than mechanical failure .

Date and time of Examination of the vehicle

On 21-08-2023 at about 11.15.A.M.


Signature of the Mechanical Expert

  
21-08-2023.

**Bhola Nath Barur**  
Automobile Engineer  
Mechanical Expert

21-08-2023.  
Date.....

Photograph Of Accidental Vehicle Bearing Registration No,  
WB-74-AX-1407.FORD ECOSPORT




Bholanath Baruri  
Automobile Engineer / Mechanical Expert

*(Signature)*  
21-08-2023.

**Bhola Nath Baruri**  
Automobile Engineer  
Mechanical Expert

SEIZURE LIST

9



REF

Roong PS

Case No-

55/23

dt

16.08.2023

U/s

279

1337/338/

427 IPC.

1. DATE &amp; TIME OF SEIZURE

On 16.08.2023 at 13:15 hrs

2. PLACE OF SEIZURE

PO Near Janta Valley Hotel  
27th Mile

3. FROM WHOM SEIZED

From PO Near Janta Valley Hotel  
27th Mile PS Roong Dist Kollamang

4. NAME OF WITNESS

- (I) Om Prakash Gupta s/o Satrughan  
Prasad Gupta of Soma ~~Gupta~~
- (II) Neger Chempasari PS Prodhon  
Neger Siligori.

Asi Prakash Thapa of  
Roong PS.

5. DESCRIPTION OF SEIZED ARTICLES :

1. One White colour Ford Vehicle bearing No- WB 74  
AX-1407.
2. P.U.C Certificate No- WB-07300550000732 of Vehicle No-  
WB 74 AX-1407. Valid up to 11.05.2024.
3. Certificate of Insurance Policy No- 27100032230060057  
Valid up to 03.04.2024.

6. SIGNATURE OF WITNESS

(I) Om Prakash Gupta

(II) Asi Prakash Thapa

SI Pradyo Kumar Rai  
Roong PS  
dt 16.08.2023

SEIZED BY ME

# SEIZURE LIST

(19)

9939

PR NO- 105/23.

REF :- Reeng P.S. Case No- 55/23 dt. 16.03.2023 u/s 279/327/  
338/427 IPC.

1. DATE & TIME OF SEIZURE : On 21.03.2023 at 17.15 hrs
2. PLACE OF SEIZURE : Reeng P.S.
3. FROM WHOM SEIZED : Being Produced by Complainant  
Pintu Lal s/o Lt. Devendra Lal  
of Babu Bara Beridanga,  
Champasari Siliguri.
4. NAME OF WITNESS :  
(I) Om Prakash Gupta s/o  
Sobhagha Prasad Gupta of  
(II) Sonar Nagar Champasari  
P.S. Pradhan Nagar Siliguri  
ASI Prakash Thapa of  
Reeng P.S.

## 5. DESCRIPTION OF SEIZED ARTICLES :

01 (One) Driving Licence bearing No. NB 732017034-  
6529 in the name of Prem Bahadur Kani s/o  
B. Bdr Kani of Pradhan Nagar N/No.2. Siliguri.  
Darjeeling.

## 6. SIGNATURE OF WITNESS

(I) OM Prakash Gupta

(II) ASI Prakash Thapa

SI Prakash K. Rai  
Reeng P.S.

21/03/2023  
SEIZED BY ME