

Form-54

[See Central Motor Vehicle Rule 1989, Rule 150(a) and (2)]

Accident Information Report.

- (1) Name of Police Station: Kalimpong
- (2) MCR No/Traffic Accident Report: 191/22 dated 12.7.22 U/S 279/337/ 427 IPC
- (3) Date, Time and place of Accident: ... on 12.7.22 . at about 14.00 hrs at Setijhora
Kalimpong under Kalimpong Dist Kalimpong . .
- (4) Name and full address of injured/deceased:.....(1) Abhinay Tewary S/O Manjay Tewary
of Kalimpong Hat Bazer PS & Dist Kalimpong 2) Abhay Tewary of do
- (5) Name of Hospital to which he/she was removed:.... Rambhi Block Primary health centre
PO& PS Reang Dist Kalimpong. .
- (6) Registration No of vehicle and type of vehicle:.... One Motor cycle bearing no WB 79-B/
0134 and one four wheeler Ultra open Truck vehicle bearing no SK 07-D/ 0309 Engine No
5LNGDICR 21NXY523802 Chassis No MAT 790220MN19892
- (7) Driving Licence Particulars:
- (a) Name and address of Driver:.... Bishnu Prasad Chettri s/o Lt Krishna Bahadur Chettri
of Pakyong khoni PS & Dist Pakyong Sikkim.
- (b) Driving license No and date of expiry:.... DL NO SK 0720200000642 valid upto 02.12.2038.
- (c) Address of issuing authority:.... Sikkim .
- (d) Badge No in case of public service vehicle:.....
- (8) Name and address of the owner of the vehicle at the time of accident: ... The registered owner
Shivji Prasad Gupta s/o Lt Rajendra Prasad Gupta of Pakyong Bazer Ps pakyang east
pakyong District . .
- (9) Name and address of Insurance Company with whom the vehicle was insured and the
particulars of the Divisional officer of the said insurance Company:.... TATA AIG I insurance
certificate company Limited
- (10) Number of insurance policy/insurance certificate and the date of validity of the insurance
policy/ insurance certificate: Policy no 01632812110000 valid up to 05.05.2023
- (11) Registration particulars of the vehicle involved:
- (a) Registration No: SK 07-D/ 0309
- b) Engine No 5LNGDICR 21NXY523802
- c) Chassis No MAT 790220MN19892
-
- (12) Route Permit Particulars:....Permit No... 176/MV/PKG Validity Period... 23.5.23 ... Route
Name.....
- (13) Action taken if any and the result thereof:Case ended in CS vide No 359/22 date
12.10.22 U/S 279/ 337/ 338/ 427 IPC IPC against aced driver Bishnu Prasad Chettri s/o
Lt Krishna Bahadur Chettri of Pakyong khoni PS & Dist Pakyong Sikkim.

Signature of reporting officer

S. Perai Karim
(R KARIM)

SI of Police
Kalimpong PS, U/Dnj

21.09.24

FIRST INFORMATION REPORT

(Under Section 154 Cr. P.C.)

6241

Dist. Kalimpang P.S. Kalimpang Year 2022 FIR No. 191/22 Date 12.7.22(i) Act Sections (ii) Act IPC Sections 279/337/338/427
(iii) Act Sections (iv) Others Acts & Sections(a) Occurrence of Offence : Day Date From 12.7.22 Date ToTime Period Time From 14.00 hrs Time To(b) Information received at P.S. Date 12.7.22 Time 19.05 hrs(c) General Diary Reference : Entry No(s) 542 Time 19.05 hrs

Type of Information :

Written / Oral

Place of Occurrence : (a) Direction and Distance from P.S. 33 Km / South West Beat No. 11 No. 76(d) Address Setijahon, Kalimpang

(e) In case outside limit of this Police Station, then the

Name of the P.S. District

Complainant / Informant :

(a) Name Mamjay Tiwari(b) Father's / Husband's Name Sp. - Nirmal Tiwari

(c) Date / Year of Birth : (d) Nationality

(e) Passport No. Date of Issue : Place of Issue

(f) Occupation

(g) Address Hat Bazar, Ps + Dist - KalimpangDetails of known / suspected / unknown accused with full particulars Driver of vehicle bearing
(Attach separate sheet, if necessary) : Registration No - SK-07-D-0309

Reasons for delay in reporting by the Complainant / Information

Particulars of properties stolen / involved (Attach separate sheet, if necessary) :

Total value of properties stolen / involved

Inquest Report / U.D. Case No., if any

FIR Contents (Attach separate sheets, if required) : The original written complaint
which is treated as FIR is enclosed herewith
reproduced over leaf.

Action taken: Since the above report reveals commission of offence(s) as mentioned at item No. 2, registered the case and took up the

Investigation / directed SI - T.T. Bhattacharya of Raing P.S. to take up

Investigation / refused investigation / transferred to P.S. on point of

Jurisdiction. FIR read over to the Complainant / Informant, admitted to be correctly recorded and a copy given to the Complainant /

Informant free of cost.

Seen & filed

Certified to be true copy

Inspector-in-charge
Kalimpang Police Station
Dist. Kalimpang

4. Signature / Thumb impression

Signature of the Officer-in-Charge

Received on 12/04/22 at 14:35h
K.P.O. No. 312 dt. 12/04/22
Inspector-in-Charge
Kalimpong Police Station
Dist. Kalimpong

सेवामा,

थाना प्रभारी
रियाडु, पी० पी०
रम्बो बजार कालिम्पोङ्ग, थाना अन्तर्गत

ता०- 12/04/2022

विषय:- दुर्घटना सम्बन्धी जानकारी।

महाशय,

म मंजय तिवारी पिला निरगुण तिवारी निवासी कालिम्पोङ्ग, हाट बजार काँ तर्फबाट तपाईंलाई यो सूचित गर्न चाहन्छौं कि मेरो दोराको बाईक नं WB 79B0134, मेरो दोरा अभय तिवारी अनि भतीज अभिनय तिवारी मेरो भतीजलाई गाडी चलाएको थियो, इनीटरन सिलिगुडी देखि कालिम्पोङ्ग आई रहेको बेला अचानक करीबन 2:00 P.M. दिउँसो सैतीकोडाँडा मा गाडी नं SK 07D0309 संग ठोक्कियो, साथै बाईक पनि क्षतिग्रस्त भयो, त्यस पछि मेरो दोरा अनि भतीजलाई निकै चोट-पटक लागियो। मेरो भतीजको टाउको चोट अनि दोराको खुट्टा नै भान्सेको हाँ त्यस पछि मेरो दोरा अनि भतीजलाई रम्बो Hospital मा लियो, तर रम्बो अस्पतालमा चोट गंभीर भएको कारण कालिम्पोङ्ग अस्पताल मा रेफर भयो। मलाई लाग्द कि गाडी नं SK 07D0309 चालकको लापरवाही अनि तेज गतिले गाडी चलाएको कारणले गर्दा यो घटना घटेको हो।

यसर्थ यस घटनालाई मध्य नजर राखीकन यस गाडी माथि कानूनी-कारवाही गरि दिनु हवसु भनी नम्र निवेदन गर्दछु।

"दान्यवाद"

तपाईंको विश्वासी
मंजय तिवारी

9382212404

Received on 12.04.2022 at 14:35h
Kalimpong P.P.O. No. 312 dt.
12.04.2022 and forwarded the same
to I/c Kalimpong P.O. to about 9

Certified to be true copy

Inspector-in-Charge
Kalimpong Police Station
Dist- Kalimpong

लेखक - Manoj K. Gupta
9002142886

SEIZURE LIST

PR. NO. 256/22

949

REF: Kalimpong P.S. case no. 191/22 dt. 12.07.2022 4/2 279/-
- 238/407 IPC

1. DATE & TIME OF SEIZURE : on 12.07.2022 at 20.35 hrs.
2. PLACE OF SEIZURE : Leang P.P.'s compound
3. FROM WHOM SEIZED : In abandoned condition
4. NAME OF WITNESS :

(I) Asst. Pankaj Thapa

(II) C/129 Kuman Thapa
Bath off Leang P.P.
cinola P.S. Kalimpong

5. DESCRIPTION OF SEIZED ARTICLES :

- (i) one (01) Bajaj Dominar D250 motor cycle bearing no. WB-49-B-0134 (Black and Ash colour) in fully damaged condition with Key.
- (ii) one (01) Tata Vitrux Truck bearing no. SK-07-D-0309 (white colour) in front right side partially damaged condition with Key.

6. SIGNATURE OF WITNESS

(I) Asst. Pankaj Thapa

Seized as a part of the case.

(II) C/129 Kuman Thapa

12/07/2022

S.I. T. T. B. W. D. H. A.

SEIZED BY ME

Leang P.P.

P.S. Kalimpong

Certified to be true

Inspector-in-charge
Kalimpong Police S
Dist- Kalimpong

SEIZURE LIST


PR. NO. 259/22

0

950

REF - Kalimpong P.S. case no. 191/22 dt. 12.07.2022 u/s 279/337/338/427 IPC.

1. DATE & TIME OF SEIZURE : on 14.07.2022 at 18.35 hr
2. PLACE OF SEIZURE : At Leang P.P.
3. FROM WHOM SEIZED : Being produced by owner of vehicle Shivji Prasad Gupta
4. NAME OF WITNESS :
(i) Mustak Ansari
W/o. Mustak Ansari
of Pakyang Bazar, opposite Tasei
Stand P.S. Pakyang East Pakyang
District.
(ii) Kinan Chatterji
W/o. H. Tilak Bdr. Chatterji
of Pakyang Near Markot
Near Hospital Road R.L. Pakyang
Pakyang Dist.
5. DESCRIPTION OF SEIZED ARTICLES :
(i) one (01) original Registration certificate of vehicle bearing no. SK-07-D-0309 (Tata Ultra) in the name of Shivji Prasad Gupta (valid upto May 2023)
(ii) one (01) Tata AIG Insurance certificate Policy no. 0163281-2110000 of vehicle no. SK-07-D-0309 (valid upto 05.05.2023)
(iii) one (01) Road tax permit no. 146/MY/PKG dt. 24.05.22 in the name of Shivji Prasad Gupta (valid upto 23.05.2023)
(iv) one (01) Authorization letter of driver Bishnu Pd. Chatterji of Pacheykhani (toeing) having DL no. SK-07-2020-0000642 issued by registered owner Shivji Prasad Gupta (valid upto 31 Dec. 2022) (v) one Driving License no. SK-07-2020-0000642 in the name of Bishnu Pd. Chatterji W/o. Ch. Krishna Bdr. Chatterji of Pacheykhani Pakyang (valid upto -02-12-2038)
6. SIGNATURE OF WITNESS

(i)  (Mustak Ansari)

(ii)  (Kinan Chatterji)

Seized on behalf of the case

Certified to be true copy

Inspector in charge

Kalimpong Police Station
Dist. Kalimpong

14/07/2022
S. T. T. B. M. H.
SEIZED BY ME,
Leang P.P.
D. N. Kalimpong

POLICE INFORMATION PROFORMA
RAMBI BLOCK PRIMARY HEALTH CENTRE
P.O. : REANG, DIST. : KALIMPONG

Particulars of Injured Person :

Name Abhinav Tewari
Religion H/B/M/C
S/o / D/o / W/o Manjay Tewari,
Address Kalimpang - Hat Bazar
Date and Time of Incident 12/07/22 at 02:00 PM
Place of Incident Sethipool
Brought by police
Date and Time of Examination 12/07/22 at 02:45 PM

INJURY REPORT

1. Brief History : RTA c/o Disoriented (?)
2. Vital Parameter : Pulse 84/min Min. / B.P. 118/70 mmHg mm. of Hg.
3. Details of Injuries : Contuse and Abrasion over (RT) knee and leg
NO other injury detected naked eye exam.
4. Treatment given : Conservative (Gt T.T, Gt Diclofenac, Dressi
X-ray (RT) knee. CT Scan knee
5. Patient Admitted / Discharge / Referred / Expired
6. Prognosis : i) Fair ii) Uncertain / Kept under observation iii) Grave To be assessed after
proper investigation

Name of M.O. Santamu Das

[Signature]
Signature

Stamp

Certified to be true copy
M 09.04.24
Inspector-in-charge
Kalimpang Police Station
Dist- Kalimpang

POLICE INFORMATION PROFORMA

RAMBI BLOCK PRIMARY HEALTH CENTRE

P.O. : REANG, DIST. : KALIMPONG

Particulars of Injured Person :

Name

Abhay Tewari

Religion

H/B/M/C

S/o / D/o / W/o

Address

Kalimpong, Hat, Bazar

Date and Time of Incident

12/07/22 at 02:00 PM

Place of Incident

Selhipool

Brought by

police

Date and Time of Examination

12/07/22 at 02:45 PM

INJURY REPORT

1. Brief History : RIM. Couldn't move (R) leg.

2. Vital Parameter : Pulse 80/min Min. / B.P. 120/74 mm. of Hg.

3. Details of Injuries : Lacerated wound below (R) lower eye lids. Bruise and Abrasion over (R) arm, forearm and palm, Ant. Chest wall. Lacerated open wound (R) foot and

4. Treatment given : Swelling over (R) Lower leg (Tibial #)

Conservative (Dressing, Ds. Ti, Ds. Diclofenac IVF M, X-ray (R) foot, leg, knee

5. Patient Admitted / Discharge / (Referred) / Expired

6. Prognosis : i) Fair ii) Uncertain / Kept under observation iii) Grave

To be assessed after proper investigation

Name of M.O. Sarlane Das

Signature

Stamp

Certified to be true copy

09-04-24

Inspector in Charge
Kalimpong Police Station
Dist- Kalimpong

MECHANICAL EXAMINATION REPORT

Date 21-07-2022

Ref.: REANG, P.P.D/R, No, 595/2022. Dated. 20-07-2022.

PS: Kalimpong.

Case No. / M.A Case No.: 191 / 2022. Dated. 12-07-2022. U/S, 279 / 337 / 338 / 427 . IPC.

Name and designation of the Motor Vehicle

Inspector/Expert: Bholanath Baruri / Automobile Engineer / Mechanical Expert .

Venue and Date of Examination: Reang Police Post compound on 21-07-2022.

1. Details of the Vehicle, (Attach close view and long view photo)

- a. Make TATA MOTORS LTD .
- b. Type ULTRA OPEN TRUCK .
- c. Model 2021 .
- d. Registration Number SK 07 D 0309 .
- e. Chassis Number MAT 790 220 M 7 N 19892 .
- f. Engine Number 5 LNGDICR 21 NYX 523802 .
- g. Colour WHITE .
- h. Distinguishing Features (Basically please write if the vehicle can be identified without the registration number like some specific Name / Painting on the Body / Windscreen etc)
Nil .

1. General Description from outside - Eye View -

- a. Point of contact between the vehicles and signs of exchange of paint-

There is no any signs of exchange of paint found at the time of examination .

- b. Description of damage caused (specify)-

Front right side show, bumper, mudguard, door is partly damage and front right side head and indicator light is broken .

- c. Any other point of interest-

Nil .

Certified to be true copy

9.4.24
Inspector-in-charge
Kalimpong Police Station
Dist- Kalimpong

Condition of Brakes (Please attach Photographs) -

a. Are the brakes OK?

Yes ☒ No ☐

b. Are they worn out?

Yes ☐ No ☒

c. Whether the brakes show wear and tear due to sudden application of the brakes at the time of accident?

Yes ☐ No ☒

d. Are there signs of brake failure which could have lead to the accident?

Yes ☐ No ☒

3. Condition of Tyres (Please attach Photographs) -

a. Do the tyres conform to the standards stipulated in MV act 1988?

Yes ☒ No ☐

b. Are the tyres worn out or resoled?

Yes ☐ No ☒

c. Do the tyres reveal any mark of skidding due to sudden deceleration by observing the wear and tear and the groove pattern?

Yes ☐ No ☒

d. Can the condition of the tyres be held responsible for the extra distance covered even after braking?

Yes ☐ No ☒

e. Were the tyres found punctured? If yes specify whether before or after the accident collision.

Yes ☐ No ☒

There is no any puncture found at the time of examination .

4. Condition of Gears -

a. Whether the gear lever, gear pinion, gear handle and clutch were in flexible state at the time of accident?

Yes ☒ No ☐

b. Whether these parts are in sufficiently lubricated condition?

Yes ☒ No ☐

5. Condition of Steering -

a. Whether steering is adequately mobile?

Yes ☒ No ☐

b. Whether the tie rod is in perfect working condition

Yes ☒ No ☐

6. Condition of Light's -

a. Whether the Head Light / Fog Light / Indicator of the vehicle are in working condition?

Yes ☒ No ☐

b. If not, is the same due to accident or were faulty even before the accident?

Light's are working properly . Except front right side head and indicator light due to accident .

7. Condition of battery :-

What is the Condition of battery?

Battery is working properly .

Certified to be true copy

29.04.24
Inspector-in-charge
Kalimpong Police Station
Dist- Kalimpong

Condition of Rear View Mirrors -

- a. Are the Rear view mirrors present inside the vehicle, and both on the left and right side of the vehicle?

Yes ☒ No ☐

9. Rear-end conspicuity in cases of rear-end collision (CMVR, 1989, RULE NO. 104)

Nil .

10. Condition of Speed Governors:-

- a. Whether speed governor have been installed?
b. Are they to operational condition?
c. Have they been tampered with?

Yes ☒ No ☐

Yes ☒ No ☐

Yes ☐ No ☒

11. Condition of the Wipers-

- a. Were the Wiper operational prior to accident as can be ascertained from the present condition?

Yes ☒ No ☐

12. Whether EDR (Even Data Recorder) present or not?

Yes ☐ No ☒

13. Whether the joining points of the Axles of the vehicle with the wheels are in proper condition or not?

Yes ☒ No ☐

14. Overloading -

Was the vehicle overload? if yes, further remarks.

Nil .

15. Any other specific observations to highlight the condition or possible cause of the accident -


From the Technical point of view the cause of accident of the above mentioned vehicle appears to be other than mechanical failure .

Date and time of Examination of the vehicle
On 21-07-2022 at about 1.30.P.M.

Signature of the Mechanical Expert


21-07-2022
Bhola Nath Barua
Automobile Engineer
Mechanical Expert

Certified to be true copy


09.04.24
Inspector-in-charge
Kalimpong Police Station
Dist- Kalimpong

BHOLA NATH BARURI

AUTOMOBILE ENGINEER
MECHANICAL EXPERT
VEHICLE ESTIMETER
(GOVT. APPROVED) MECH. REG. NO. 1120

**Photograph of Vehicle bearing registration no
SK 07 D 0309 TATA ULTRA TRUCK**

M/S. B. N. BARURI MECHANICAL

EXPERT AND

C/O. M/S. ANIL TRADING

SEVOKE ROAD, SILIGURI-73

DARJEELING

(WEST BENGAL GOVT.) REG. NO. L

Date...21-07-2022...



Bholanath Baruri
Automobile Engineer Mechanical Expert

(Signature)
21-07-2022
Bhola Nath Baruri
Automobile Engineer
Mechanical Expert

Certified to be true copy

(Signature)
09-04-24
Inspector-in-charge
Kalimpong Police Station
Dist- Kalimpong